

County Surveyor's Record, Douglas County, Oregon

17226

Subdivision of Sec. 19,
T. 21 S., R. 12 W., Willamette Meridian, Oregon

CHAINS	
10.35	Bottom of descent, slopes NW.; asc. 95 ft. over SW. slope.
13.60	Top of ascent, slopes NW.; desc. 5 ft. over gentle, broken NW. slope.
19.97	Point for the center S 1/16 sec. cor. of sec. 19. Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, with aluminum cap mkd. <div style="text-align: center;"> C S 1/16 S 19 C 1981 </div> from which A pine, 7 ins. diam., bears S. 62 1/2° E., 18 1/2 lks. dist., mkd. CS 1/16 S19 BT. A pine, 10 ins. diam., bears N. 84 1/2° W., 13 lks. dist., mkd. CS 1/16 S19 BT. Descend 165 ft. over NW. slope, changing to broken N. slope.
39.94	Point for the center 1/4 sec. cor. of sec. 19, at intersection with the E. and W. center line. Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, with aluminum cap mkd. <div style="text-align: center;"> T 21 S R 12 W C 1/4 S 19 1981 </div> from which A pine, 20 ins. diam., bears N. 36° E., 36 lks. dist., mkd. C 1/4 S19 BT. A spruce, 35 ins. diam., bears S. 26 1/2° W., 66 lks. dist., mkd. C 1/4 S19 BT. Set a steel fence post alongside aluminum post. Descend slightly over N. slope.
41.50	Leave undergrowth, enter sand dunes, edge bears NE. and SW.; desc. 30 ft. over rolling sand dunes.
61.65	Bottom of descent, slopes W.; asc. 170 ft. over S. slope.
65.35	Top of ascent, slopes S. 65° W.; enter scattering timber and dense undergrowth, edge bears NE. and SW.; desc. 45 ft. over broken NW. slope.
75.57	The 1/4 sec. cor. of secs. 18 and 19.
8.00	From the 1/4 sec. cor. of secs. 19 and 24. S. 89° 56' E., on a mean bearing, on the E. and W. center line of sec. 19. Ascend slightly over rolling sand dunes. Enter heavy timber and light undergrowth, edge bears N. and S.; asc. 175 ft. over broken W. slope.