

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 21 S., R. 7 W., Willamette Meridian, Oregon

17234

CHAINS									
	N. 1° 20' E., beginning new measurement.								
	Ascend 185 ft. over SE. slope.								
11.50	Head of ravine, drains S. 35° E.; asc. 120 ft. over SE. slope.								
14.50	Ridge, bears NE. and SW.; desc. 65 ft. over NW. slope, also dirt road, 15 lks. wide, bears NE. and SW.								
17.15	Ravine, drains N. 60° W.; asc. 20 ft. over SW. slope.								
19.42	The cor. of secs. 25, 26, 35, and 36, perpetuated and recorded by Wilford N. Haines, Registered Land Surveyor No. 239, in 1960, monumented with a 3/4 in. "T" shaped iron rod, firmly set, projecting 2 ins. above the ground, with an aluminum washer mkd. "Wilford N. Haines Survey Point 239", from which the remaining original bearing tree								
	A fir, 53 ins. diam., bears N. 50° W., 114 lks. dist., with healed blaze.								
	and bearing trees mkd. by Haines								
	A fir, 10 ins. diam., bears N. 41° E., 39 1/2 lks. dist., with healed blaze.								
	A fir, 14 ins. diam., bears S. 70 1/4° E., 42 1/2 lks. dist., with healed blaze.								
	A fir, 12 ins. diam., bears S. 13 1/2° W., 38 lks. dist., with healed blaze.								
	A fir, 8 ins. diam., bears N. 11° W., 30 lks. dist., with healed blaze.								
	At the corner point								
	Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.								
	<div style="display: flex; align-items: center; justify-content: center;"> <div style="text-align: left; margin-right: 20px;"> <p style="font-size: small; margin: 0;"><i>Found OK D. BAKER 12/91 M 114-26</i></p> </div> <table style="border-collapse: collapse;"> <tr> <td style="padding: 0 5px;">T 21 S</td> <td style="padding: 0 5px;">R 7 W</td> </tr> <tr> <td style="padding: 0 5px; border-right: 1px solid black;">S 26</td> <td style="padding: 0 5px;">S 25</td> </tr> <tr> <td style="padding: 0 5px; border-right: 1px solid black;">S 35</td> <td style="padding: 0 5px;">S 36</td> </tr> <tr> <td colspan="2" style="text-align: center; padding: 0 5px;">1981</td> </tr> </table> </div>	T 21 S	R 7 W	S 26	S 25	S 35	S 36	1981	
T 21 S	R 7 W								
S 26	S 25								
S 35	S 36								
1981									
	Deposit the "T" shaped iron rod alongside the iron post.								
	Land, mountainous.								
	Soil, rocky clay.								
	Timber, fir, yew, hemlock, oak, alder, maple, chinquapin, madrone, cedar, and ash; undergrowth, poison oak, fern, salal, Oregon grape, blackberry, salmonberry, arrowwood, hazel, huckleberry, vine maple, hawthorne, scotch broom, cascara, willow, and young timber.								
	N. 2° 54' W., bet. secs. 25 and 26.								
	Ascend 5 ft. over SW. slope, through heavy timber and dense undergrowth.								
0.45	Spur, slopes N. 80° W.; desc. 105 ft. over NW. slope.								
3.35	Ravine, drains S. 60° W.; asc. 225 ft. over SW. slope.								