

# County Surveyor's Record, Douglas County, Oregon

**17273** Dependent Resurvey, Portion of Subdivisional Lines,  
T. 30 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

T 30 S    R 9 W

S 5	S 4
S 8	S 9

1962

from which the remains of the original bearing trees

A sawed fir stump, 35 ins. diam., bears N. 83° E.,  
38 1/2 lks. dist., no marks remaining.

A root hole, bears N. 36 1/2° W., 31 lks. dist.,  
with a down fir alongside, 70 ins. diam., with healed  
blaze.

and the remains of a bearing tree mkd. by Jelley

A root hole, bears N. 12 1/2° E., 36 lks. dist., with  
a down cedar alongside, 38 ins. diam., with  
decayed blaze.

The corner is located in a logged area; no other suitable  
trees available within limits.

N. 0° 59' W., bet. secs. 4 and 5, marking and blazing the  
true line.

Ascend 35 ft. over nearly level land, across logged area.

16.50

Top of ascent, slopes NW.; desc. 30 ft. over NW. slope.

20.145

Point for the S 1/16 sec. cor. of secs. 4 and 5.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 40 ins. in  
the ground, the top 12 ins. below the surface, with brass  
cap mkd.

S 1/16	
S 5	S 4
1980	

from which

A fir, 10 ins. diam., bears S. 47 1/4° E., 27 lks.  
dist., mkd. S 1/16 S4 BT.

A fir, 40 ins. diam., bears N. 25 1/2° W., 62 lks.  
dist., mkd. S 1/16 S5 BT.

The corner is located in south edge of dirt road, 15 lks.  
wide, bears N. 80° E. and S. 80° W.

Descend 5 ft. over nearly level land.

20.60

Bottom of descent, slopes NW.; asc. 40 ft. over SW.  
slope.

26.70

Spur, slopes NW.; desc. 65 ft. over NW. slope.

40.29

Point for the 1/4 sec. cor. of secs. 4 and 5, at propor-  
tionate distance; there is no remaining evidence of the  
original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in  
the ground, with brass cap mkd.