

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17282**
T. 30 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
	<p>A grand fir, 23 ins. diam., bears N. 55° W., 46 lks. dist., mkd. W 1/16 S19 BT.</p> <p>A fir, 35 ins. diam., bears S. 13° W., 44 lks. dist., mkd. W 1/16 S30 BT.</p> <p>Descend 70 ft. over NW. slope.</p>
20.15	Creek, 3 lks. wide, course N. 20° E.; asc. 135 ft. over SE. slope.
26.70	Ridge, bears NE. and SW.; desc. 40 ft. over NW. slope.
38.70	Spur, slopes NW.; desc. 70 ft. over SW. slope.
42.14	The cor. of secs. 19, 24, 25, and 30, on the W. bdy. of the Tp.
	<p>Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, maple, oak, madrone, alder, and chinquapin; undergrowth, salal, Oregon grape, poison oak, rhododendron, vine maple, ferns, and grasses.</p>
<p>Subdivision of Section 19, T. 30 S., R. 8 W., Willamette Meridian, Oregon</p>	
	<p>From the 1/4 sec. cor. of secs. 19 and 30.</p> <p>N. 0° 24' W., on the N. and S. center line of sec. 19, marking and blazing true line.</p> <p>Descend 80 ft. over broken N. slope, through heavy timber and dense undergrowth.</p>
14.60	Boulder creek, 10 lks. wide, course W.; asc. 65 ft. over SW. slope.
16.50	Gravelled road, 30 lks. wide, bears E. and W.
19.98	Point for the center S 1/16 sec. cor. of sec. 19.
	<p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p style="margin: 0;">C S 1/16 S 19 C 1980</p> </div>
	<p>from which</p> <p>A fir, 9 ins. diam., bears S. 42 1/2° E., 31 lks. dist., mkd. CS 1/16 S19 BT.</p> <p>A white fir, 11 ins. diam., bears N. 26° W., 34 lks. dist., mkd. CS 1/16 S19 BT.</p> <p>Ascend 395 ft. over SW. slope.</p>
39.96	Point for the center 1/4 sec. cor. of sec. 19, at intersection with the E. and W. center line.
	<p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p>