

County Surveyor's Record, Douglas County, Oregon

17307

Dependent Resurvey, Portion of Subdivisional Lines,
T. 31 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

Land, mountainous.
Soil, rocky clay.
Timber, fir, cedar, hemlock, pine, yew, oak, maple, ash,
and alder; undergrowth, vine maple, fern, poison oak,
Oregon grape, salal, arrowwood, hazel, blackberry,
huckleberry, salmonberry, thimbleberry, wild rose,
manzanita, cascara, rhododendron, and young timber.

From the cor. of sec. 3, 4, 9, and 10.

N. 89° 10' W., bet. secs. 4 and 9.

Descend 205 ft. over broken W. slope, through heavy timber
and dense undergrowth.

4.60 Dirt road, 30 lks. wide, bears N. and S.

5.10 Catching Creek, 10 lks. wide, course N.; asc. 500 ft.
over broken NE. slope.

23.25 Spur, slopes N. 50° E.; desc. 235 ft. over broken NW.
slope.

35.90 Creek, 10 lks. wide, course N. 40° E.; asc. 235 ft. over
broken SE. slope.

39.34 Point for the 1/4 sec. cor. of secs. 4 and 9, at
proportionate dist.; there is no remaining evidence of
the original cor.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in
the ground, with brass cap mkd.

T 31 S R 6 W
1/4 $\frac{S 4}{S 9}$

1980

from which

A fir, 45 ins. diam., bears N. 19 1/2° W., 42 lks.
dist., mkd. 1/4 S4 BT.

A fir, 19 ins. diam., bears S. 1 1/2° W., 28 lks.
dist., mkd. 1/4 S9 BT.

Ascend 150 ft. over SE. slope.

46.55 Spur, slopes S. 50° E.; desc. 10 ft. over SW. slope.

48.15 Ravine, drains S. 35° E.; asc. 155 ft. over broken SE.
slope.

56.05 Spur, slopes S. 15° W.; desc. 5 ft. over SW. slope.

57.05 Ravine, drains S. 30° E.; asc. 55 ft. over SE. slope.

58.70 Spur, slopes S. 60° E.; asc. 170 ft. over broken SE.
slope.

66.25 Ridge, bears N. 30° E. and S. 20° W.; desc. 305 ft. over
broken NW. slope, also dirt road, 15 lks. wide, bears
N. 30° E. and S. 20° W.

78.45 Ravine, drains S. 75° W.; asc. 5 ft. over SE. slope.