

County Surveyor's Record, Douglas County, Oregon

17327

Subdivision of Section 33,
T. 21 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

A twin oak, 34 ins. diam., bears S. 47 3/4° W.,
226 lks. dist., with healed blaze.

A fir stump, 27 ins. diam., bears N. 54 1/4° W.,
110 lks. dist., with healed blaze.

and a bearing tree mkd. by person(s) unknown and recorded
by Godfrey

A fir, 24 ins. diam., bears S. 65° W., 46 lks.
dist., with healed double blaze.

and a bearing tree mkd. by Godfrey

A fir, 42 ins. diam., bears N. 30 1/2° W., 30 lks.
dist., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in
the ground, with brass cap mkd.

T 21 S R 5 W
1/4 $\frac{S 33}{S 4}$
T 22 S R 5 W

1981

from this point, Douglas County Surveyors Office Horizontal
control station "HEATHER", bears N. 73° 25' E.,
27.09 chs. dist., monumented with a concrete post, 8 ins.
square, firmly set, the top flush with the surface of the
ground, with brass tablet, 2 1/2 ins. diam., set in top,
mkd. HEATHER 1979.

From this same point, the intersection of wire fences,
extending N. and S. 80° E., bears S. 70° E., 0.14 chs.
dist.

N. 0° 18' W., on the N. and S. center line of sec. 33.

Ascend 250 ft. over broken SW. slope, through open
pasture land.

19.90 Woven wire fence, extends E. and W.

28.60 Spur, slopes S. 20° E.; asc. 135 ft. over broken SE.
slope.

39.99 Point for the center 1/4 sec. cor. of sec. 33, at intersec-
tion with the E. and W. center line.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in
the ground, with brass cap mkd.

T 21 S R 5 W
C 1/4 S 33

1981

from which

A fir, 9 ins. diam., bears S. 3 3/4° W., 255 lks.
dist., mkd. C 1/4 S33 BT.

A triple cedar, 16 ins. diam., bears N. 50 1/4° W.,
67 lks. dist., mkd. C 1/4 S33 BT.