

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17342**  
T. 24 S., R. 1 W., Willamette Meridian, Oregon

**CHAINS**

A sawed fir stump, 25 ins. diam., bears S. 63° E.,  
24 lks. dist., with a healed blaze.

A sawed fir stump, 14 ins. diam., bears S. 45° W.,  
20 lks. dist., with axe marks visible on an  
opened blaze.

A sawed fir stump, 26 ins. diam., bears N. 47° W.,  
15 lks. dist., with scribe marks S18 visible on  
an opened blaze.

and a bearing tree mkd. by Godfrey

A hemlock, 10 ins. diam., bears S. 49° W., 13 lks.  
dist., with fragmentary scribe marks visible on  
partially healed blaze.

and new bearing trees

A hemlock, 8 ins. diam., bears S. 5 1/2° E., 40 lks.  
dist., mkd. T24S R1W S20 BT.

A hemlock, 8 ins. diam., bears N. 73 1/2° W., 43 lks.  
dist., mkd. T24S R1W S18 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, maple, hemlock, oak, chinquapin,  
alder, madrone, and yew; undergrowth, salal, vine maple,  
Oregon grape, rhododendron, fern, arrowwood, hazel,  
blackberry, salmonberry, manzanita, and young timber.

Subdivision of Section 20,  
T. 24 S., R. 1 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of secs. 20 and 29.

N. 0° 05' W., on the N. and S. center line of sec. 20.


Ascend 15 ft. over broken SW. slope, through heavy timber  
and dense undergrowth.

0.90 Spur, slopes S. 80° W.; asc. 60 ft. over broken SW. slope.

4.85 Spur, slopes N. 70° W.; desc. 165 ft. over NW. slope.

8.75 Creek, 4 lks. wide, course S. 60° W.; asc. 265 ft. over  
SE. slope.

19.89 The center S 1/16 sec. cor. of sec. 20, established by  
Howard W. Johnstone, Registered Land Surveyor, No. 498,  
in 1977, and accepted as the cor., monumented with an  
iron rod, 5/8 in. diam., firmly set, projecting 8 ins.  
above ground, with aluminum cap mkd.



from which the remains of the bearing trees mkd. by  
Johnstone