

# County Surveyor's Record, Douglas County, Oregon

17345

Subdivision of Sec. 20,  
T. 24 S., R. 1 W., Willamette Meridian, Oregon

CHAINS	
14.95	Spur, slopes S. 60° W.; desc. 95 ft. over NW. slope.
19.58	The center 1/4 sec. cor. of sec. 20.
	S. 89° 12' W., beginning new measurement.
	Descend 575 ft. over NW. slope.
4.55	Gravelled road, 25 lks. wide, bears N. 15° E. and S. 35° E.
16.50	Creek, 5 lks. wide, course S. 30° W.; asc. 80 ft. over NE. slope.
19.52	Point for the center W 1/16 sec. cor. of sec. 20.
	Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.
	$C \frac{W \ 1/16}{S \ 20} C$ 1982
	from which
	A fir, 36 ins. diam., bears N. 39 1/2° E., 75 lks. dist., mkd. CW 1/16 S20 BT.
	A yew, 4 ins. diam., bears S. 73 1/2° E., 125 lks. dist., mkd. X BT.
	Ascend 330 ft. over NE. slope.
27.40	Gravelled road, 25 lks. wide, bears N. 10° E. and S. 20° W.
28.70	Gravelled road, 25 lks. wide, bears N. 50° E. and S. 40° W.
31.50	Spur, slopes S.; desc. 280 ft. over SW. slope.
33.20	Gravelled road, 25 lks. wide, bears N. 5° W. and S. 10° E.
39.04	The 1/4 sec. cor. of secs. 19 and 20.
	From the E 1/16 sec. cor. of secs. 20 and 29.
	N. 0° 17' W., on the N. and S. center line of the SE 1/4 of sec. 20.
	Ascend 340 ft. over SE. slope, through heavy timber and dense undergrowth.
9.45	Spur, slopes S. 60° W.; desc. 230 ft. over broken NW. slope.
19.88	Point for the SE 1/16 sec. cor. of sec. 20, established and recorded by Howard W. Johnstone, Registered Land Surveyor, No. 498, in 1977, and accepted as the cor. point as determined at record bearing and dist. from bearing trees mkd. by Johnstone
	A fir, 24 ins. diam., bears N. 38° E., 23 lks. dist., with scribe marks SE 1/16 S20 BT visible on open blaze.