

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of E. Bdy., 17354
T. 25 S., R. 2 W., Willamette Meridian, Oregon

CHAINS

A root hole, bears S. 30° E., 31 lks. dist., with a down sawed fir stump alongside, 24 ins. diam., with fragmentary scribe marks visible on open blaze.

A root hole, bears S. 35° W., 13 lks. dist., with a down fir alongside, 27 ins. diam., no marks visible.

From this point, the SW. cor. of T. 24 S., R. 1 W., bears S. 89° 52' W., 13.97 chs. dist., hereinafter described.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, cedar, hemlock, maple, oak, chinquapin, alder, and madrone; undergrowth, salal, Oregon grape, vine maple, poison oak, rhododendron, fern, and grasses.

Dependent Resurvey of a Portion of the North Boundary,
T. 25 S., R. 1 W., Willamette Meridian, Oregon

(Restoring the survey
by Carl S. Nicklin and Winfield S. Chapman in 1897,
and the resurvey
by C. Albert White and Levi E. Tallett in 1951-63)

From the cor. of secs. 5, 6, 31, and 32, on the N. bdy. of the Tp., perpetuated and recorded by Vernon R. Tracy, Deputy Douglas County Surveyor, in 1966, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

County Surveyors Office
T 24 S
S 31 | S 32 R 1 W
S 6 | S 5
T 25 S
1966

from which the remains of the original bearing trees

A root hole, bears N. 63° E., 22 lks. dist., with a down hemlock alongside, 16 ins. diam., with healed blaze.

A root hole, bears S. 55° E., 9 lks. dist., with a down hemlock alongside, 18 ins. diam., with healed blaze.

A sawed fir stump, 18 ins. diam., bears S. 87 1/2° W., 70 lks. dist., with healed blaze.

A root hole, bears N. 59° W., 62 lks. dist., with a down cedar stump alongside, 19 ins. diam., with healed blaze.

and bearing trees mkd. by Tracy

A hemlock, 14 ins. diam., bears N. 27° E., 90 1/2 lks. dist., with fragmentary scribe marks visible on open blaze.