

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 1 W., Willamette Meridian, Oregon

17358

CHAINS

A fir, 22 ins. diam., bears N. 64 1/2° E., 29 lks. dist., with healed blaze.

A fir, 15 ins. diam., bears S. 27 1/2° E., 21 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 25 S	T 25 S	
R 2 W	S 6	CC
S 1	S 7	
	R 1 W	
		1981

Deposit the iron pipe alongside the iron post.

From this point, the 1/4 sec. cor. of sec. 1 only, T. 25 S., R. 2 W., bears N. 0° 11' W., 7.21 chs. dist., hereinbefore described.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, cedar, maple, oak, alder, chinquapin, and madrone; undergrowth, salal, rhododendron, vine maple, poison oak, fern, and grasses.

From the cor. of secs. 5, 6, 7, and 8, perpetuated and recorded by James W. Byron, Deputy Douglas County Surveyor, in 1960, monumented with an iron post, 1 1/4 ins. diam., loosely set, projecting 14 ins. above ground, with brass cap mkd.

T 25 S	R 1 W	
S 6	S 5	
S 7	S 8	
		1960

from which the remains of an original bearing tree

A root hole, bears N. 35° E., 15 lks. dist., with a down maple alongside, 10 ins. diam., with fragmentary scribe marks visible on decayed blaze.

and the remains of bearing trees mkd. by Byron

A fir, 10 ins. diam., bears S. 80 1/2° E., 67 1/2 lks. dist., with healed double blaze.

A chinquapin, 14 ins. diam., bears S. 66° W., 48 lks. dist., with healed double blaze.

A cedar snag, 14 ins. diam., bears N. 34° W., 54 lks. dist., with fragmentary scribe marks visible on partially open blaze.

and a tree not of known record

A fir snag, 16 ins. diam., bears N. 49° E., 59 lks. dist., with scribe marks T25S R1W S5 BT visible on open blaze.