

County Surveyor's Record, Douglas County, Oregon

17359 Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 1 W., Willamette Meridian, Oregon

CHAINS	
	<p>Raise a mound of stone, 5 ft. base, to top, around the iron post.</p> <p>N. 3° 03' E., bet. secs. 5 and 6.</p> <p>Ascend 390 ft. over broken S. slope, through clear-cut area.</p>
9.40	Spur, slopes S. 50° E.; desc. 5 ft. over NE. slope.
11.80	Ravine, drains S. 60° E.; asc. 75 ft. over SE. slope.
17.20	Ravine, drains S. 70° E.; asc. 370 ft. over broken SE. slope.
36.40	Spur, slopes N. 70° E.; desc. 215 ft. over NE. slope.
41.31	<p>Point for the 1/4 sec. cor. of secs. 5 and 6, at proportionate dist.; there is no remaining evidence of the original cor.</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>T 25 S R 1 W</p> <p>1/4</p> <p>S 6 S 5</p> <p>1981</p> </div> <p>from which</p> <p style="margin-left: 40px;">A cedar, 6 ins. diam., bears S. 78° E., 44 1/2 lks. dist., mkd. 1/4 S5 BT.</p> <p style="margin-left: 40px;">A hemlock, 6 ins. diam., bears N. 59 1/2° W., 137 1/2 lks. dist., mkd. 1/4 S6 BT.</p> <p>Descend 35 ft. over NE. slope.</p>
43.70	Creek, 3 lks. wide, course N. 85° E.; asc. 80 ft. over SE. slope.
52.10	Spur, slopes S. 65° E.; desc. 255 ft. over NE. slope.
59.40	Creek, 4 lks. wide, course S. 70° E.; asc. 770 ft. over SE. slope.
80.60	Spur, slopes S. 70° E.; desc. 20 ft. over NE. slope.
83.11	<p>The cor. of secs. 5, 6, 31, and 32, on the N. bdy. of the Tp.</p> <p>Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, maple, oak, madrone, alder, chinquapin, and live oak; undergrowth, salal, Oregon grape, vine maple, poison oak, rhododendron, fern, and grasses.</p>
	<p>The point for the 1/4 sec. cor. of sec. 6 only, T. 25 S., R. 1 W., is at proportionate dist. on the N. bdy. of sec. 6.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p>