

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17370**
T. 30 S., R. 5 W., Willamette Mer., Oregon

CHAINS

The corner is located in a woven wire fence, extending N. and S.

Descend 25 ft. over NW. slope.

21.60 Power line, bears N. 45° E. and S. 45° W.

22.55 Road intersection, gravelled roads, 30 lks. wide, bears N. 10° E., N. 80° E., S. 10° E., and S. 40° W.

23.95 Dry creek bed, 10 lks. wide, course S. 50° W.; asc. 190 ft. over broken SE. slope.

39.68 The 1/4 sec. cor. of secs. 29 and 30, perpetuated and recorded by John H. Markham, Jr., Registered Engineer, No. 2880, in 1950, subsequently perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1963, and by R. B. Kimberling and Steven J. Flause, Deputy County Surveyors, in 1978, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 30 S	Reset
1/4 S 30	1978
R 5 W	S 29
1963	

from which the remains of an original bearing tree

An oak snag, size indeterminate, bears N. 75° E., 40 lks. dist., no marks visible.

and a bearing tree mkd. by Markham

A madrone, 16 ins. diam., bears N. 25° W., 16 lks. dist., with illegible scribe marks visible on partially healed blaze.

and the remains of a bearing tree mkd. by Byron

A fir snag, 16 ins. diam., bears N. 59° E., 18 lks. dist., no marks visible.

and a bearing tree and a reference monument mkd. by Kimberling and Flause

A madrone, 10 ins. diam., bears N. 56° E., 54 lks. dist., with scribe marks 1/4 S29 CS BT visible on bark blaze.

An iron rod, 1/2 in. diam., firmly set, projecting 6 ins. above ground, bears N. 8 3/4° W., 5 1/2 lks. dist., with aluminum cap mkd. DOUGLAS COUNTY SURVEYOR 1978.

Land, mountainous.

Soil, rocky clay.

Timber, oak, madrone, alder, ash, fir, cedar, maple, pine, yew, and chinquapin; undergrowth, poison oak, blackberry, huckleberry, arrowwood, hazel, salmonberry, Oregon grape, salal, and young timber.