

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17380**
T. 28 S., R. 4 W., Willamette Mer., Oregon

CHAINS

and bearing trees mkd. by James W. Byron, Deputy Douglas County Surveyor, in 1957

A white oak, 9 ins. diam., bears N. 88° E.,
7 lks. dist., with healed blaze.

A white oak, 12 ins. diam., bears S. 35° E.,
86 1/2 lks. dist., with healed blaze.

A white oak, 12 ins. diam., bears S. 80 1/2° W.,
44 lks. dist., with healed blaze.

A fir, 22 ins. diam., bears N. 32 1/2° W.,
142 lks. dist., with healed blaze.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, cedar, maple, oak, madrone,
chinquapin, and alder; undergrowth, salal, Oregon grape,
rhododendron, vine maple, poison oak, fern, and grasses.

Subdivision of Section 27,
T. 28 S., R. 4 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of secs. 27 and 34.


N. 0° 06' E., on the N. and S. center line of sec. 27.

Ascend 25 ft. over SW. slope, through scattering timber
and dense undergrowth.

6.90 Spur, slopes N. 80° W.; desc. 575 ft. over NW. slope.

20.40 Point for the center S 1/16 sec. cor. of sec. 27.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in
the ground, with brass cap mkd.



from which

A fir, 11 ins. diam., bears N. 76° E., 64 lks.
dist., mkd. CS 1/16 S27 BT.

A fir, 12 ins. diam., bears S. 57° W., 93 1/2 lks.
dist., mkd. CS 1/16 S27 BT.

Descend 25 ft. over NW. slope.

29.90 North Myrtle Creek, 12 lks. wide, course S. 20° E.; asc.
75 ft. over SE. slope.

39.30 Asphalt surfaced road, 30 lks. wide, bears N. 50° E. and
S. 50° W.

39.45 Two strand power line, bears N. 60° E. and S. 60° W.

40.80 Point for the center 1/4 sec. cor. of sec. 27, at inter-
section with the E. and W. center line.