

County Surveyor's Record, Douglas County, Oregon

17401

Subdivision of Section 23,
T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
	<p>A power pole, No. A 105, bears N. 24° E., 14 lks. dist.</p> <p>An oak, 13 ins. diam., bears N. 52° W., 178 lks. dist., with fragmentary scribe marks visible on partially healed blaze.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>S. 89° 51' W., beginning new measurement.</p> <p>Descend over SW. slope.</p>
3.70	Tenmile Creek, 15 lks. wide, course S. 50° E.; asc. over gradual NE. slope.
19.99	<p>The center 1/4 sec. cor. of sec. 23.</p> <p>Ascend over broken NE. slope.</p>
31.25	Creek, 5 lks. wide, course N. 20° E.; asc. over broken NE. slope.
40.04	<p>Point for the center W 1/16 sec. cor. of sec. 23.</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> $C \frac{W \ 1/16}{S \ 23} C$ <p>1982</p> </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 9 ins. diam., bears N. 55 3/4° E., 49 1/2 lks. dist., mkd. CW 1/16 S23 BT.</p> <p style="margin-left: 40px;">A cedar, 7 ins. diam., bears S. 30 1/2° W., 16 lks. dist., mkd. CW 1/16 S23 BT.</p> <p>Ascend over NE. slope.</p>
40.25	Spur, slopes N. 55° E.; desc. over broken NW. slope.
53.05	Ravine, drains N. 55° E.; asc. over NE. slope.
60.09	The 1/4 sec. cor. of secs. 22 and 23.
	<hr style="border: 0.5px solid black;"/> <p>From the center W 1/16 sec. cor. of sec. 23.</p> <p>N. 0° 07' W., on the N. and S. center line of the NW 1/4 of sec. 23.</p> <p>Ascend along E. slope, through heavy timber and dense undergrowth.</p>
0.50	Spur, slopes N. 40° E.; desc. over broken NW. slope, changing to NE. slope.
19.93	<p>Intersect the S. bdy. of Donation Land Claim No. 40, point for the crossing closing cor.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p>