

County Surveyor's Record, Douglas County, Oregon

17413

Dependent Resurvey, Portion of Subdivisional Lines,
T. 33 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

(Restoring the survey by William H. Byars in 1882, the survey by Oscar F. Thiel in 1901, the remonumentation by Rollin D. Aanrud, John M. Jelley, and Lynn M. Roseberry in 1969-70, and the resurvey by Rollin D. Aanrud and Lynn M. Roseberry, Cadastral Surveyors, in 1975)

From the cor. of secs. 10, 11, 14, and 15, perpetuated and recorded by the Douglas County Surveyor's Office, in 1968, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 33 S	R 7 W
S 10	S 11
S 15	S 14
1968	

from which the remains of three original bearing trees

A root hole, bears S. 74° E., 34 lks. dist., alongside of which is lying a decayed alder, size indeterminate, no marks visible on decayed blaze.

A root hole, bears S. 42° W., 17 lks. dist., alongside of which is lying a fir, 52 ins. diam., no marks visible.

A fir, 50 ins. diam., bears N. 9° W., 43 lks. dist., with a healed blaze.

and bearing trees mkd. by the County Surveyor's Office

A maple, 12 ins. diam., bears N. 67° E., 33 lks. dist., with healed blaze.

A fir, 50 ins. diam., bears S. 55° W., 49 1/2 lks. dist., with healed blaze.

No other suitable trees available within limits.

N. 0° 01' W., bet. secs. 10 and 11.

Ascend 230 ft. over SE. slope, through heavy timber and dense undergrowth.

10.90 Ridge, bears N. 70° E. and S. 70° W., also dirt road, 15 lks. wide, bears same; desc. 190 ft. over NW. slope.

39.96 Point for the 1/4 sec. cor. of secs. 10 and 11, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 33 S	R 7 W
1/4	
S 10	S 11
1981	

from which

A fir, 38 ins. diam., bears N. 75 1/2° E., 55 lks. dist., mkd. 1/4 S11 BT.