

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 33 S., R. 7 W., Willamette Meridian, Oregon 17428

CHAINS	
81.34	<p>The cor. of secs. 18 and 19 only, on the W. bdy. of the Tp.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, pine, cedar, oak, madrone, chinquapin, alder, and maple; undergrowth, poison oak, manzanita, ceonothus, hazel, huckleberry, salal, Oregon grape, and young timber.</p>
	<p>From the 1/4 sec. cor. of secs. 7 and 18, monumented with a broken granite stone, 18 x 16 x 12 ins., loosely set, 4 ins. in the ground, mkd. 1/4 on N. face, from which the original bearing trees</p> <p style="padding-left: 40px;">A madrone, 10 ins. diam., bears N. 10° W., 21 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A sugar pine, 22 ins. diam., bears S. 29° E., 27 lks. dist., with healed blaze.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 33 S    R 7 W           1/4 <math>\frac{S 7}{S 18}</math>                   1981</p> <p>Deposit the corner stone alongside the iron post.</p> <p>N. 89° 08' W., bet. secs. 7 and 18.</p> <p>Ascend 460 ft. over E. slope, through heavy timber and dense undergrowth.</p>
16.50	Spur ridge, bears N. 40° W. and S. 40° E., slopes S. 40° W.; desc. 890 ft. over W. slope.
17.05	Dirt road, 15 lks. wide, bears N. 10° W. and S. 10° E.
21.20	Dirt road, 15 lks. wide, bears N. and S.
40.50	Reuben Creek, 10 lks. wide, course S.; asc. 40 ft. over E. slope.
41.30	<p>The cor. of secs. 7 and 18 only, on the W. bdy. of the Tp., monumented with the original granite stone, 16 x 12 x 10 ins., firmly set 6 ins. in the ground, with faint chisel marks visible on N. and S. sides, from which the remains of the original bearing trees</p> <p style="padding-left: 40px;">A live oak stump, 6 ins. diam., bears N. 57° E., 14 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A fir, 60 ins. diam., bears S. 89° E., 11 lks. dist., with illegible scribe marks visible on bark blaze.</p> <p style="padding-left: 40px;">A cedar snag, 14 ins. diam., bears S. 35° W., 15 lks. dist., no marks visible on partly healed double blaze.</p> <p style="padding-left: 40px;">A broken topped cedar, 18 ins. diam., bears N. 5° W., 32 lks. dist., with healed blaze.</p>