

County Surveyor's Record, Douglas County, Oregon

17443

Subdivision of Sec. 35,
T. 26 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	Ascend 110 ft. over SW. slope, through heavy timber and dense undergrowth.
2.65	Gravelled road, 25 lks. wide, bears N. 75° E. and S. 75° W.
6.25	Spur, slopes S. 80° W.; desc. 25 ft. over NW. slope.
6.60	Gravelled road, 25 lks. wide, bears N. 35° E. and S. 35° E., in curve.
12.85	Ravine, drains S. 60° W.; asc. 95 ft. over broken SE. slope.
19.85	Point for the SE 1/16 sec. cor. of sec. 35, at intersection with the E. and W. center line of the SE 1/4. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd. SE 1/16 S 35 1981 from which A fir, 26 ins. diam., bears N. 70° E., 48 1/2 lks. dist., mkd. SE 1/16 S35 BT. A cedar, 19 ins. diam., bears N. 55° W., 16 lks. dist., mkd. SE 1/16 S35 BT. Ascend 70 ft. over SE. slope.
24.00	Gravelled road, 25 lks. wide, bears N. 60° W. and S. 75° E.
27.80	Spur, slopes SW.; desc. 55 ft. over NW. slope.
31.35	Head of ravine, drains N. 80° W.; asc. 15 ft. over broken SW. slope.
32.30	Power transmission line, bears N. 75° W. and S. 75° E.
35.10	Spur, slopes N. 25° W.; desc. 25 ft. over NE. slope.
39.71	The center E 1/16 sec. cor. of sec. 35.
	From the S 1/16 sec. cor. of secs. 35 and 36. N. 89° 54' W., on the E. and W. center line of the SE 1/4 of sec. 35. Descend 325 ft. over SW. slope, through heavy timber and dense undergrowth.
3.20	Gravelled road, 25 lks. wide, bears N. 20° W. and S. 40° E.
14.00	Dirt road, 25 lks. wide, bears N. 50° W. and S. 50° E.
17.30	Gravelled road, 25 lks. wide, bears N. 35° W. and S. 35° E.
20.15	The SE 1/16 sec. cor. of sec. 35. Descend 200 ft. over broken SW. slope.