

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines 17454
T. 20 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

A hemlock, 14 ins. diam., bears N. 67 1/2° W.,
49 lks. dist., with a healed blaze.

The corner point is located at edge of timber, bears S.
and W.

N. 1° 50' W., beginning new measurement.

Continue over nearly level ground, across logged area.

12.85 Enter timber, edge bears SW. and E.

20.45 Descend over NW. slope.

25.40 Windy Creek, 5 lks. wide, course S. 10° W.; asc. over SE.
slope.

26.10 Windy Creek Road, gravelled surface, 25 lks. wide, bears
N. 10° E. and S. 15° W.

38.10 Spur, slopes E.; desc. over NE. slope.

40.35 Ravine, drains E.; asc. over SE. slope.

40.79 The cor. of secs. 22, 23, 26, and 27, monumented with an
iron post, 2 ins. diam., with a brass cap, firmly set,
projecting 6 ins. above ground, alongside of which is a
steel fence post, firmly set, projecting 4 ft. above
ground, with brass cap mkd.

T 20 S	R 9 W
S 22	S 23
S 27	S 26
1953	

from which the remains of bearing trees mkd. by Tillman
and Gawron

An alder snag, 22 ins. diam., bears N. 9° E., 37
lks. dist., with scribe marks S23 B visible on
a decayed bark blaze.

A cedar, 21 ins. diam., bears S. 47° E., 50 lks.
dist., with scribe marks T20S visible on a
partially decayed blaze.

A cedar, 20 ins. diam., bears S. 4° W., 71 lks.
dist., with fragmentary scribe marks visible
on a decayed blaze.

An alder, 20 ins. diam., bears N. 52° W., 59 lks.
dist., with scribe marks T20S R9W S22 BT visible
on a bark blaze.

and a new bearing tree

An alder, 23 ins. diam., bears N. 67° E., 80
lks. dist., mkd. T20S R9W S23 BT.

Land, mountainous.
Soil, sandy clay loam.
Timber, fir, hemlock, cedar, alder, and maple; under-
growth, vine maple, huckleberry, salmonberry, arrowwood,
salal, Oregon grape, and fern.

From the cor. of secs. 26, 27, 34, and 35.