

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines, **17458**  
T. 20 S., R. 9 W., Willamette Meridian, Oregon

CHAINS													
5.25	Left bank of West Fork of Smith River, bears same; asc. over broken S. slope.												
16.50	Top of ascent, slopes S.; continue over nearly level land.												
20.72	Point for the N 1/16 sec. cor. of secs. 27 and 28.  Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with aluminum cap mkd.  <div style="text-align: center;"> <table style="margin: auto;"> <tr><td colspan="2">N 1/16</td></tr> <tr><td>S 28</td><td>  S 27</td></tr> <tr><td colspan="2">1982</td></tr> </table> </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 21 ins. diam., bears N. 64° E., 36 lks. dist., mkd. N 1/16 S27 BT.</p> <p style="margin-left: 40px;">A fir, 20 ins. diam., bears N. 50 1/4° W., 27 lks. dist., mkd. N 1/16 S28 BT.</p> <p>Continue over nearly level ground.</p>	N 1/16		S 28	S 27	1982							
N 1/16													
S 28	S 27												
1982													
35.50	Descend over NE. slope.												
41.44	The cor. of secs. 21, 22, 27, and 28, monumented with an iron post, 2 ins. diam., firmly set, projecting 24 ins. above ground, with brass cap mkd.  <div style="text-align: center;"> <table style="margin: auto;"> <tr><td>T 20 S</td><td></td><td>R 9 W</td></tr> <tr><td>S 21</td><td> </td><td>S 22</td></tr> <tr><td>S 28</td><td> </td><td>S 27</td></tr> <tr><td colspan="3">1957</td></tr> </table> </div> <p>from which bearing trees mkd. by Tillman and Gawron</p> <p style="margin-left: 40px;">A fir, 30 ins. diam., bears N. 7 1/4° E., 41 lks. dist., with a healed blaze.</p> <p style="margin-left: 40px;">A fir, 14 ins. diam., bears S. 82 1/2° E., 14 lks. dist., with fragmentary scribe marks visible on a decayed blaze.</p> <p style="margin-left: 40px;">A fir, 28 ins. diam., bears S. 32 1/2° W., 31 lks. dist., with a healed blaze.</p> <p style="margin-left: 40px;">A fir, 26 ins. diam., bears N. 83 1/2° W., 18 lks. dist., with a healed blaze.</p> <p>Land, mountainous. Soil, sandy clay loam. Timber, fir, hemlock, cedar, alder, maple, myrtle, and dogwood; undergrowth, vine maple, huckleberry, rhododendron, hazel, salal, Oregon grape, and fern.</p>	T 20 S		R 9 W	S 21		S 22	S 28		S 27	1957		
T 20 S		R 9 W											
S 21		S 22											
S 28		S 27											
1957													
	From the cor. of secs. 22, 23, 26, and 27.  S. 89° 17' W., bet. secs. 22 and 27.  Ascend over broken E. slope, through heavy timber and dense undergrowth.												
11.50	Spur ridge, bears N. and S.; desc. over broken W. slope.												
19.66	Point for the E 1/16 sec. cor. of secs. 22 and 27.												