

# County Surveyor's Record, Douglas County, Oregon

17479

Subdivision of Section 24,  
T. 19 S., R. 9 W., Willamette Meridian, Oregon

CHAINS	
	<p>from which</p> <p style="margin-left: 40px;">A fir, 43 ins. diam., bears N. 72 1/2° E., 38 lks. dist., mkd. X BT.</p> <p style="margin-left: 40px;">A fir, 49 ins. diam., bears N. 19° W., 40 lks. dist., mkd. CS 1/16 S24 BT.</p> <p>Ascend over broken S. slope.</p>
24.70	<p>Spur ridge, bears N. 50° W. and S. 50° E.; asc. along broken E. slope.</p>
28.55	<p>Spur, slopes S. 80° E.; desc. over broken NE. slope.</p>
40.64	<p>Point for the center 1/4 sec. cor. of sec. 24, at intersection with the E. and W. center line.</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.</p> <p style="text-align: center;">T 19 S    R 9 W C 1/4 S 24 1981</p>
	<p>from which</p> <p style="margin-left: 40px;">A hemlock, 20 ins. diam., bears S. 58 1/2° W., 51 lks. dist., mkd. C 1/4 S24 BT.</p> <p style="margin-left: 40px;">A fir, 40 ins. diam., bears N. 42 1/2° W., 40 1/2 lks. dist., mkd. C 1/4 S24 BT.</p> <p>Descend 25 ft. over N. slope.</p>
41.10	<p>Creek, 4 lks. wide, course E.; asc. over broken S. slope.</p>
56.45	<p>Spur ridge, bears N. 70° W. and S. 70° E.; desc. over NE. slope.</p>
59.80	<p>Ravine, drains N. 80° E.; asc. over S. slope.</p>
60.94	<p>Point for the center N 1/16 sec. cor. of sec. 24.</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.</p> <p style="text-align: center;">C N 1/16   S 24 C 1981</p>
	<p>from which</p> <p style="margin-left: 40px;">A fir, 23 ins. diam., bears N. 86° E., 40 lks. dist., mkd. X BT.</p> <p style="margin-left: 40px;">A fir, 22 ins. diam., bears N. 19° W., 28 lks. dist., mkd. CN 1/16 S24 BT.</p> <p>Ascend over S. slope.</p>
62.00	<p>Spur, slopes S. 80° E.; desc. over NE. slope.</p>
65.25	<p>Ravine, drains S. 70° E.; asc. over broken S. slope.</p>
81.24	<p>The 1/4 sec. cor. of secs. 13 and 24.</p>