

County Surveyor's Record, Douglas County, Oregon

17509

Subdivision of Section 1,
T. 27 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
7.25	Creek, 5 lks. wide, course S. 5° E.; desc. over broken SW. slope.
19.82	Point for the center E 1/16 sec. cor. of sec. 1. Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd. <div style="text-align: center;"> $C \frac{E \ 1/16}{S \ 1} C$ <p>1982</p> </div> from which A cedar, 13 ins. diam., bears N. 41° E., 79 1/2 lks. dist., mkd. CE 1/16 S1 BT. A fir, 5 ins. diam., bears S. 48 1/2° E., 110 lks. dist., mkd. X BT. Descend over broken SW. slope.
24.40	Creek, 5 lks. wide, course S. 15° W.; desc. over broken SW. slope.
39.64	The center 1/4 sec. cor. of sec. 1. Descend over SW. slope.
48.65	Bond Creek, 3 lks. wide, course S. 20° E.; asc. over SE. slope.
59.055	Point for the center W 1/16 sec. cor. of sec. 1. Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd. <div style="text-align: center;"> $C \frac{W \ 1/16}{S \ 1} C$ <p>1982</p> </div> from which A madrone, 10 ins. diam., bears S. 12 1/2° W., 26 lks. dist., mkd. CW 1/16 S1 BT. A black oak, 4 ins. diam., bears N. 72° W., 23 1/2 lks. dist., mkd. X BT. Ascend over SE. slope.
77.15	Spur, slopes S.; desc. over SW. slope.
78.47	The 1/4 sec. cor. of secs. 1 and 2.
	From the E 1/16 sec. cor. of secs. 1 and 12. N. 0° 53' E., on the N. and S. center line of the SE 1/4 of sec. 1. Ascend over broken SE. slope, through heavy timber and dense undergrowth.
8.30	Spur, slopes S. 50° W.; desc. over NW. slope.
15.65	Bottom of descent, slopes S. 70° W.; asc. over SW. slope.