

County Surveyor's Record, Douglas County, Oregon

17515

Dependent Resurvey, Portion of W. Bdy.,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

Beginning at the cor. of secs. 19, 24, 25, and 30, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 2 ins. above ground, with brass cap mkd.

T 25 S	
R 5 W	R 4 W
S 24	S 19
S 25	S 30
1957	

from which the remains of the original bearing trees

A sawed fir stump, 55 ins. diam., bears S. 39° E., 120 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

A fir stump, 70 ins. diam., bears S. 19° W., 27 lks. dist., with healed blaze.

and remains of bearing trees mkd. in 1957

A fir, 20 ins. diam., bears N. 16 1/2° E., 205 1/2 lks. dist., with healed blaze.

A sawed cedar stump, 18 ins. diam., bears S. 75° E., 198 lks. dist., with healed blaze. (Record, 201 lks.)

A sawed fir stump, 48 ins. diam., bears N. 33 1/4° W., 56 lks. dist., with healed blaze.

and new bearing trees

A fir, 4 ins. diam., bears S. 28° E., 12 1/2 lks. dist., mkd. X BT.

A fir, 6 ins. diam., bears S. 58° W., 130 lks. dist., mkd. T25S R5W S25 BT.

A fir, 6 ins. diam., bears N. 67 1/4° W., 140 lks. dist., mkd. T25S R5W S24 BT.

N. 0° 04' W., bet. secs. 19 and 24, marking and blazing the true line.

Descend over NW. slope, through scattering timber and moderate undergrowth.

0.55 Creek, 1 lk. wide, course NW.; asc. over broken SW. slope.

16.40 Spur, slopes W.; desc. over NW. slope.

19.81 The S 1/16 sec. cor. of secs. 19 and 24, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

S 1/16	
S 24	S 19
1957	

from which bearing trees mkd. in 1957

A fir, 22 ins. diam., bears S. 12 1/2° E., 54 lks. dist., with healed blaze.

A fir, 17 ins. diam., bears N. 12 1/2° W., 65 lks. dist., with healed blaze.