

County Surveyor's Record, Douglas County, Oregon

17517 Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

A fir rootcrown, 40 ins. diam., bears S. 17° W.,
300 lks. dist., no marks remain.

and the remains of the bearing trees mkd. in 1957

A cedar, 30 ins. diam., bears S. 57 1/2° E., 164 lks.
dist., with scribe marks T25S R4W S33 BT visible
on open blaze.

A root hole, bears S. 37° W., 132 lks. dist., with
an uprooted fir alongside, 20 ins. diam., no
marks visible. (Record, 142 lks.)

A root hole, bears N. 64 1/4° W., 214 lks. dist., with
an uprooted fir alongside, 10 ins. diam., with
fragmentary scribe marks visible on open blaze.

and new bearing trees

A fir, 16 ins. diam., bears N. 85° E., 252 lks.
dist., mkd. T25S R4W S28 BT.

A cedar, 10 ins. diam., bears S. 51° W., 355 lks.
dist., mkd. T25S R4W S32 BT.

An oak, 11 ins. diam., bears N. 86 1/2° W., 534 lks.
dist., mkd. T25S R4W S29 BT.

N. 4° 26' W., bet. secs. 28 and 29, marking and blazing
the true line.

Ascend broken S. slope, through heavy timber and dense
undergrowth.

5.60 Ridge, bears N. 50° E. and S. 50° W.; desc. over broken
NW. slope.

19.25 Point for the S 1/16 sec. cor. of secs. 28 and 29, at
proportionate distance.

Set aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins.
in the ground, with aluminum cap mkd.

S 1/16
S 29 | S 28
1982

from which

A cedar, 9 ins. diam., bears N. 10° E., 24 1/2 lks.
dist., mkd. S 1/16 S28 BT.

A fir, 14 ins. diam., bears S. 35 1/2° W., 21 1/2 lks.
dist., mkd. S 1/16 S29 BT.

The corner is located in a ravine, drains N. 60° W.

Ascend over broken SW. slope.

19.45 The witness cor. to the S 1/16 sec. cor. of secs. 28 and
29, monumented with an iron post, 2 1/2 ins. diam., firmly
set, projecting 4 ins. above ground, with brass cap mkd.

S 1/16
WC
S 29 ↓ S 28
1957