

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17520**  
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS  
20.72

The W 1/16 sec.cor. of secs. 29 and 32, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

W 1/16  $\frac{S\ 29}{S\ 32}$   
1957

from which the remaining bearing tree mkd. in 1957

A yew, 12 ins. diam., bears S. 51 3/4° E., 64 lks. dist., with scribe marks W 1/16 S32 BT visible on open blaze.

and a new bearing tree

A fir, 7 ins. diam., bears N. 18 1/2° E., 30 lks. dist., mkd. W 1/16 S29 BT.

S. 87° 17' W., beginning new measurement.

Descend over W. slope.

0.30 Ravine, drains N.; asc. over E. slope.

13.25 Spur, slopes N.; desc. over W. slope.

17.80 Creek, 1 lk. wide, course NW.; asc. over NE. slope.

20.70 The cor. of secs. 29, 30, 31, and 32, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 3 ins. above ground, with brass cap mkd.

T 25 S R 4 W  
 $\frac{S\ 30\ | S\ 29}{S\ 31\ | S\ 32}$   
1957

from which the remains of bearing trees mkd. in 1957

A hemlock, 12 ins. diam., bears N. 46° E., 33 lks. dist., with healed blaze.

A sawed fir stump, 24 ins. diam., bears S. 50° E., 62 lks. dist., with healed blaze.

A sawed fir stump, 24 ins. diam., bears S. 4 3/4° W., 192 lks. dist., with healed blaze.

A root hole, bears N. 36° W., 368 lks. dist., with an uprooted hemlock alongside, 16 ins. diam., no marks visible.

and new bearing trees

A hemlock, 6 ins. diam., bears S. 72° E., 28 lks. dist., mkd. T25S R4W S32 BT.

A fir, 7 ins. diam., bears S. 61° W., 11 1/2 lks. dist., mkd. T25S R4W S31 BT.

A fir, 8 ins. diam., bears N. 72° W., 14 lks. dist., mkd. T25S R4W S30 BT.

Land, mountainous.  
Soil, rocky clay.