

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17522**
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

6.90	Sutherlin Creek, 5 lks. wide, course S. 70° W.; asc. over SE. slope.
20.10	<p>The N 1/16 sec. cor. of secs. 29 and 30, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.</p> <p style="text-align: center;">N 1/16 S 30 S 29 1957</p> <p>from which the remains of bearing trees mkd. in 1957</p> <p style="padding-left: 40px;">A madrone, 20 ins. diam., bears N. 21° E., 171 lks. dist., with fragmentary scribe marks visible on partially healed blaze.</p> <p style="padding-left: 40px;">A sawed fir stump, 18 ins. diam., bears S. 6 1/4° W., 140 lks. dist., with scribe marks BT visible on open blaze.</p> <p>and new bearing trees</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears S. 64 3/4° E., 58 lks. dist., mkd. N 1/16 S29 BT.</p> <p style="padding-left: 40px;">A fir, 5 ins. diam., bears S. 57 1/4° W., 41 lks. dist., mkd. N 1/16 S30 BT.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 4° 23' W., beginning new measurement.</p> <p>Ascend SE. slope.</p>
7.40	Gravelled road, 20 lks. wide, bears N. 60° E. and S. 70° W.
20.08	<p>The cor. of secs. 19, 20, 29, and 30, perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1964, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.</p> <p style="text-align: center;">COUNTY SURVEYORS OFFICE T 25 S S 19 S 20 S 30 S 29 1964</p> <p>from which the remains of the original bearing trees</p> <p style="padding-left: 40px;">A root hole, bears S. 45° E., 21 lks. dist., with an uprooted madrone alongside, 16 ins. diam., no marks visible on decayed blaze.</p> <p style="padding-left: 40px;">A root hole, bears N. 50° W., 31 lks. dist., with an uprooted fir alongside, 20 ins. diam., with scribe marks T2 R4W S19 visible on open blaze.</p> <p>and the remains of bearing trees mkd. in 1957</p> <p style="padding-left: 40px;">A root hole, bears N. 51° E., 130 lks. dist., with an uprooted fir alongside, 32 ins. diam., with healed blaze.</p> <p style="padding-left: 40px;">A sawed fir stump, 20 ins. diam., bears S. 49 1/2° E., 104 lks. dist., with healed blaze.</p>