

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17524**
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

An ash, 23 ins. diam., bears S. 26° W., 21 lks.
dist., mkd. 1/4 S29 BT.

N. 88° 36' W., bet. secs. 20 and 29.

Ascend over SE. slope, through scattering timber and
dense undergrowth.

10.60 Ravine, drains S. 40° E.; asc. SE. slope.

21.09 The W 1/16 sec. cor. of secs. 20 and 29, monumented with
an iron post, 2 1/2 ins. diam., firmly set, projecting 1 in.
above ground, with brass cap mkd.

W 1/16 $\frac{S\ 20}{S\ 29}$
1957

from which the remains of bearing trees mkd. in 1957

A fir snag, 30 ins. diam., bears N. 44 1/2° W., 44
lks. dist., with healed blaze.

A sawed fir stump, 21 ins. diam., bears S. 22 1/2° W.,
106 lks. dist., no marks visible.

and bearing trees mkd. by Karen Reed, Deputy County
Surveyor, in 1978

A cedar, 10 ins. diam., bears N. 8° E., 39 1/2 lks.
dist., with scribe marks W 1/16 S20 CS BT visible
on open blaze.

A fir, 14 ins. diam., bears S. 39 1/2° E., 73 lks.
dist., with scribe marks W 1/16 S29 CS visible
on open blaze.

N. 88° 19' W., beginning new measurement.

Ascend over broken SE. slope.

19.60 Ridge, bears N. 20° E. and S. 20° W.; desc. over W.
slope.

21.09 The cor. of secs. 19, 20, 29, and 30.

Land, mountainous.
Soil, rocky clay.
Timber, fir, hemlock, cedar, yew, madrone, oak, ash,
alder, chinquapin, and maple; undergrowth, poison oak,
vine maple, arrowwood, hazel, salal, Oregon grape,
huckleberry, blackberry, salmonberry, and young timber.

S. 89° 00' W., bet. secs. 19 and 30.

Descend over broken W. slope, through heavy timber and
dense undergrowth.

19.15 Gravelled road, 15 lks. wide, bears N. 50° W. and
S. 5° E.

32.20 Gravelled road, 25 lks. wide, bears N. and S. 10° W.

32.50 Sutherland Creek, 10 lks. wide, course N.; asc. over E.
slope, changing to SE. slope.