

County Surveyor's Record, Douglas County, Oregon

17527 Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS											
1.60	Ravine, drains N. 40° W.; desc. along W. slope, changing to NW. slope.										
4.60	Creek, 2 lks. wide, course W.; asc. over SW. slope.										
7.95	Spur, slopes W.; desc. over NW. slope.										
13.50	Creek, 2 lks. wide, course S. 60° W.; asc. over SE. slope.										
20.35	<p>The cor. of secs. 17, 18, 19, and 20, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr><td>T 25 S</td><td></td></tr> <tr><td>R 4 W</td><td></td></tr> <tr><td>S 18 S 17</td><td></td></tr> <tr><td>S 19 S 20</td><td></td></tr> <tr><td>1957</td><td></td></tr> </table> </div> <p>from which the remains of the original bearing trees</p> <p style="margin-left: 40px;">A root hole, bears N. 32° E., 27 lks. dist., with an uprooted fir alongside, 80 ins. diam., no marks visible.</p> <p style="margin-left: 40px;">A fir, 36 ins. diam., bears S. 42° E., 64 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A fir, 61 ins. diam., bears S. 54 1/4° W., 62 lks. dist., with scribe marks S19 visible on bark blaze.</p> <p>and bearing trees mkd. in 1957</p> <p style="margin-left: 40px;">A fir, 35 ins. diam., bears N. 61° E., 137 lks. dist., with healed blaze. (Record, 138 1/2 lks.)</p> <p style="margin-left: 40px;">A fir, 18 ins. diam., bears N. 70° W., 55 lks. dist., with healed blaze. (Record, 57 lks.)</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, cedar, maple, oak, ash, madrone, maple, chinquapin, and yew; undergrowth, poison oak, vine maple, salmonberry, huckleberry, blackberry, wild rose, arrowwood, hazel, salal, Oregon grape, and young timber.</p>	T 25 S		R 4 W		S 18 S 17		S 19 S 20		1957	
T 25 S											
R 4 W											
S 18 S 17											
S 19 S 20											
1957											
7.40	<p>S. 89° 19' W., bet. secs. 18 and 19.</p> <p>Ascend over SE. slope, through heavy timber and dense undergrowth.</p> <p>Spur, slopes S.; desc. over broken SW. slope.</p>										
19.95	<p>The E 1/16 sec. cor. of secs. 18 and 19, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 3 ins. above ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr><td>E 1/16</td><td>S 18</td></tr> <tr><td></td><td>S 19</td></tr> <tr><td></td><td>1957</td></tr> </table> </div> <p>from which the remains of bearing trees mkd. in 1957</p> <p style="margin-left: 40px;">A root hole, bears N. 74° W., 83 lks. dist., with an uprooted fir alongside, 30 ins. diam., with healed blaze.</p>	E 1/16	S 18		S 19		1957				
E 1/16	S 18										
	S 19										
	1957										