

County Surveyor's Record, Douglas County, Oregon

Subdivision, Section 19,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

17530

CHAINS

A fir, 15 ins. diam., bears N. 8 1/2° E., 14 lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

C
N 1/16 | S 19
C
1982

from which a new bearing tree

A fir, 12 ins. diam., bears S. 77 1/2° W., 17 1/2 lks. dist., mkd. CN 1/16 S19 BT.

Reset the iron rod alongside the iron post.

N. 0° 44' E., beginning new measurement.

Descend over NE. slope.

13.75 Creek, 5 lks. wide, course N. 75° W.; asc. over SW. slope.

15.70 Creek, 2 lks. wide, course N. 65° W.; asc. over SW. slope.

20.22 The 1/4 sec. cor. of secs. 18 and 19.

From the 1/4 sec. cor. of secs. 19 and 20.

S. 89° 29' W., on the E. and W. center line of sec. 19.

Ascend along S. slope, through heavy timber and dense undergrowth.

14.85 Spur, slopes S. 20° W.; desc. over SW. slope.

19.67 Point for the center E 1/16 sec. cor. of sec. 19

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

C $\frac{E\ 1/16}{S\ 19}$ C
1982

from which

A fir, 13 ins. diam., bears S. 36 1/2° E., 251 lks. dist., mkd. CE 1/16 S19 BT.

A fir, 16 ins. diam., bears N. 3/4° W., 86 1/2 lks. dist., mkd. CE 1/16 S19 BT.

Descend over broken NW. slope, changing to SW. slope.

39.34 The center 1/4 sec. cor. of sec. 19.

Descend over SW. slope.

41.10 Creek, 1 lk. wide, course S. 35° W.; asc. over nearly level land.