

County Surveyor's Record, Douglas County, Oregon

17532

Subdivision, Section 19,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
	<p>S. 89° 33' W., beginning new measurement.</p> <p>Descend over NW. slope.</p>
4.50	Ravine, drains N. 10° W.; asc. over NE. slope.
19.82	The center N 1/16 sec. cor. of sec. 19.
	<p>From the center S 1/16 sec. cor. of sec. 19.</p> <p>S. 89° 50' W., on the E. and W. centerline of the SW 1/4 of sec. 19.</p> <p>Ascend over broken SW. slope, through heavy timber and dense undergrowth.</p>
1.60	Dirt road, 15 lks. wide, bears N. 25° W. and S. 25° E.
5.35	Sutherland Creek, 15 lks. wide, course N. 20° W.; asc. over NE. slope.
13.35	Spur, slopes N. 5° W.; desc. over NW. slope.
16.90	Ravine, drains N.; asc. over broken NE. slope.
35.10	Spur, slopes N. 10° E.; desc. over broken NW. slope.
38.57	The S 1/16 sec. cor. of secs. 19 and 24, on the W. bdy. of the Tp.
	<p>Subdivision of Section 29, T. 25 S., R. 4 W., Willamette Meridian, Oregon</p>
	<p>From the 1/4 sec. cor. of secs. 29 and 32.</p> <p>N. 4° 01' W., on the N. and S. center line of sec. 29.</p> <p>Ascend over SW. slope, through heavy timber and dense undergrowth.</p>
0.75	Spur, slopes W.; asc. over broken SW. slope.
15.25	Spur, slopes W.; desc. over broken NW. slope.
18.86	Point for the center S 1/16 sec. cor. of sec. 29.
	<p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> $\begin{array}{c} C \\ S\ 1/16 \quad \quad S\ 29 \\ C \\ 1982 \end{array}$ </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 24 ins. diam., bears S. 77° E., 57 lks. dist., mkd. CS 1/16 S29 BT.</p> <p style="margin-left: 40px;">A fir, 24 ins. diam., bears S. 76° W., 29 lks. dist., mkd. CS 1/16 S29 BT.</p> <p>Descend over broken NW. slope.</p>
37.72	Point for the center 1/4 sec. cor. of sec. 29, at intersection with the E. and W. center line.