

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines **17540**
T. 23 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

T 23 S R 4 W

S 14	S 13
S 23	S 24

1971

from which the remains of bearing trees mkd. by Wilford N. Haines, Registered Land Surveyor, No. 239, in 1963

A fir, 27 ins. diam., bears N. 9 1/2° E., 57 1/2 lks. dist., with healed blaze.

A sawed fir stump, 26 ins. diam., bears S. 17 1/4° E., 42 1/2 lks. dist., with healed blaze.

A fir, 25 ins. diam., bears S. 55° W., 95 1/2 lks. dist., with healed blaze.

A fir, 15 ins. diam., bears N. 74 1/2° W., 13 lks. dist., with healed blaze.

N. 0° 37' E., bet. secs. 13 and 14, marking and blazing the true line.

Descend over broken NW. slope, through heavy timber and dense undergrowth.

1.95 Creek, 2 lks. wide, course N. 65° W.; desc. over broken NW. slope.

19.95 The S 1/16 sec. cor. of secs. 13 and 14, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

S 1/16

S 14	S 13
------	------

1971

from which bearing trees mkd. by Jelley

A fir, 10 ins. diam., bears N. 46° E., 32 lks. dist., with healed blaze.

A fir, 11 ins. diam., bears S. 43 1/2° W., 8 lks. dist., with healed blaze.

N. 0° 46' E., beginning new measurement.

Descend over broken NW. slope.

14.60 Creek, 5 lks. wide, course N. 30° W.; asc. over SW. slope.

19.95 The 1/4 sec. cor. of secs. 13 and 14, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

Fao. ox D. PEEL
6-91 M 113 - 42

1/4

S 14	S 13
------	------

T 23 S R 4 W

1971