County Surveyor's Record, Douglas County, Oregon

17575

Dependent Resurvey of
a Portion of the Subdivisional Lines,
T. 33 S., R. 6 W., Willamette Meridian, Oregon.

CHAINS

(Restoring the survey by Wells Lake and George W. Hyde in 1856, the survey by William H. Byars in 1882, the resurvey by Hans W. Thielsen and Joseph S. Gawron in 1958-63, the resurvey and remonumentation by Joseph S. Gawron in 1963-64, and the resurvey by Rollin D. Aanrud in 1976)

Beginning at the cor. of secs. 4, 5, 32, and 33, on the S. bdy. of the Tp., perpetuated and recorded by Leland P. Lovejoy, Registered Land Surveyor, No. 262, in 1952, from original evidence which is no longer in existence, subsequently perpetuated and recorded by Roger T. Reece, Deputy County Surveyor in 1972, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

R 6 W

32	33	T 33
5	4	T 34

from which bearing trees mkd. by Reece

A fir, 11 ins. diam., bears S. 82 1/2° E., 31 1/2 lks. dist., with healed double blaze.

A fir, 14 ins. diam., bears S. 21° E., 21 1/2 lks. dist., with healed double blaze.

A fir, 7 ins. diam., bears N. 86 1/2° W., 9 lks. dist., with healed double blaze.

A fir, 19 ins. diam., bears N. 1° W., 30 1/2 lks. dist., with healed double blaze.

and new bearing trees

A madrone, 11 ins. diam., bears N. 7 1/2° E., 79 1/2 lks. dist., mkd. T33S R6W S33 BT.

A fir, 12 ins. diam., bears S. 53 3/4° W., 29 1/2 lks. dist., mkd. T34S R6W S5 BT.

N. 4° 08' E., bet. secs. 32 and 33, marking and blazing the true line.

Ascend over broken SE. slope, through heavy timber and dense undergrowth.

15.80 Ridge, bears N. 30° E. and S. 30° W.; desc. over NW. slope.

21.795 Point for the S 1/16 sec. cor. of secs. 32 and 33.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.

S 1/16

S 32 | S 33

1982

from which

A fir, 9 ins. diam., bears S. 40° E., 23 1/2 lks. dist., mkd. S 1/16 S33 BT.