

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of  
a Portion of the Subdivisional Lines, **17578**  
T. 33 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	S. 88° 08' W., bet. secs. 28 and 33.
	Descend over broken SW. slope, through heavy timber and dense undergrowth.
3.30	Ravine, drains S.; asc. over broken SE. slope.
6.90	Spur, slopes S. 5° E.; desc. over broken SW. slope.
11.60	Creek, 2 lks. wide, course SE.; asc. over SE. slope.
13.30	Dirt road, 10 lks. wide, bears N. 5° W. and S. 5° E.
20.80	Top of ascent, slopes SW.; desc. over broken W. slope.
32.00	Dirt road, 10 lks. wide, bears N. 25° W. and S. 5° E.
40.49	Point for the 1/4 sec. cor. of secs. 28 and 33, at proportionate distance; there is no remaining evidence of the original cor.
	Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.
	T 33 S    R 6 W 1/4 $\frac{S\ 28}{S\ 33}$ 1982
	from which
	A fir, 18 ins. diam., bears S. 71 3/4° E., 65 1/2 lks. dist., mkd. 1/4 S33 BT.
	A fir, 16 ins. diam., bears N. 8 1/4° W., 55 1/2 lks. dist., mkd. 1/4 S28 BT.
	Descend over W. slope.
41.30	Creek, 5 lks. wide, course S.; asc. over broken NE. slope.
70.80	Ridge, bears N. 15° W. and S. 15° E., also intersection of dirt roads, 30 lks. wide, bears N. 15° W., S. 15° E., N. 50° W., and S. 35° E.; desc. over SW. slope.
80.98	The cor. of secs. 28, 29, 32, and 33.
	Land, mountainous. Soil, rocky clay. Timber, fir, pine, cedar, oak, chinquapin, maple, and madrone; undergrowth, poison oak, manzanita, ceanothus, Oregon grape, salal, grass, and weeds.
	N. 1° 13' E., bet. secs. 28 and 29.
	Ascend over SW. slope, through heavy timber and dense undergrowth.
8.00	Spur, slopes N. 80° W.; asc. over broken SW. slope.
10.50	Dirt road, 30 lks. wide, bears NE. and S. 20° E., in curve.
12.20	Spur, slopes S. 75° W.; desc. over NW. slope.