

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of
a Portion of the Subdivisional Lines, **17582**
T. 33 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	Land, mountainous. Soil, rocky clay. Timber, pine, fir, cedar, oak, and madrone; undergrowth, poison oak; ceanothus, Oregon grape, manzanita, salal, grass, and weeds.
	From the cor. of secs. 20, 21, 29, and 28. S. 89° 48' W., bet. secs. 20 and 29. Ascend over NE. slope, through heavy timber and dense undergrowth.
3.00	Spur, slopes N. 20° E.; desc. over NW. slope.
28.20	Ravine, drains N. 25° E.; asc. over broken NE. slope.
39.74	The 1/4 sec. cor. of secs. 20 and 29, determined at record distance from the remains of the original bearing trees A root hole, bears N. 45° E., 22 lks. dist., alongside of which is lying a madrone, 15 ins. diam., no marks visible on open and burned blaze. (Record, N. 35° E.) A fir snag, 35 ins. diam., bears S. 8° W., 61 lks. dist., with illegible scribe marks visible on bark blaze.
	At the corner point Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 12 ins. in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with aluminum cap mkd.
	T 33 S R 6 W 1/4 $\frac{S 20}{S 29}$ 1982
	from which new bearing trees A fir, 12 ins. diam., bears S. 60 1/2° W., 43 1/2 lks. dist., mkd. 1/4 S29 BT. A fir, 20 ins. diam., bears N. 14° W., 82 lks. dist., mkd. 1/4 S20 BT.
	<hr style="width: 20%; margin: 0 auto;"/> N. 89° 05' W., beginning new measurement. Ascend over broken NE. slope.
3.30	Spur, slopes N. 25° W.; desc. over broken NW. slope.
19.86	Point for the W 1/16 sec. cor. of secs. 20 and 29. Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.
	W 1/16 $\frac{S 20}{S 29}$ 1982