

County Surveyor's Record, Douglas County, Oregon

17587

Dependent Resurvey of
a Portion of the Subdivisional Lines,
T. 33 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	<p>A fir, 26 ins. diam., bears N. 47 3/4° E., 47 lks. dist., mkd. 1/4 S17 BT.</p> <p>A cedar, 7 1/2 ins. diam., bears S. 27° W., 84 1/2 lks. dist., mkd. 1/4 S20 BT.</p> <p>Descend over NW. slope.</p>
49.00	Creek, 3 lks. wide, course S.; asc. over SE. slope.
50.50	Spur, slopes S. 10° E.; desc. over NW. slope.
52.80	Creek, 4 lks. wide, course S. 30° E.; asc. over SE. slope.
77.90	Ridge, bears N. 50° W. and S. 50° E.; desc. over SW. slope.
79.54	The cor. of secs. 17, 18, 19, and 20.
	<p>Land, mountainous. Soil, rocky clay. Timber, fir, pine, cedar, oak, chinquapin, maple, and madrone; undergrowth, poison oak, Oregon grape, manzanita, salal, young timber, grass, and weeds.</p>
	<p>S. 88° 40' W., bet. secs. 18 and 19.</p> <p>Descend over broken SW. slope, through heavy timber and dense undergrowth.</p>
3.90	Ravine, drains S. 30° E.; asc. over SE. slope.
9.10	Spur, slopes S. 20° E.; desc. over SW. slope.
12.20	Ravine, drains S. 30° E.; asc. over SE. slope.
29.90	Spur, slopes S. 10° W.; desc. over SW. slope.
38.40	Dirt road, 15 lks. wide, bears N. 30° E. and S. 30° W.
40.77	Point for the 1/4 sec. cor. of secs. 18 and 19, at propor- tionate distance; there is no remaining evidence of the original cor.
	<p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, with aluminum cap mkd.</p> <p style="text-align: center;">T 33 S R 6 W 1/4 $\frac{S 18}{S 19}$</p> <p style="text-align: center;">1982</p>
	<p>from which</p> <p>A tanoak, 9 ins. diam., bears N. 51 1/4° E., 62 lks. dist., mkd. 1/4 S18 BT.</p> <p>A fir, 9 ins. diam., bears S. 30 3/4° W., 5 lks. dist., mkd. 1/4 S19 BT.</p> <p>Descend over SW. slope.</p>
41.00	Abandoned dirt road, 15 lks. wide, bears N. 10° E. and S. 10° W.