

County Surveyor's Record, Douglas County, Oregon

17593 Dependent Resurvey, Portion of Subdivisional Lines,
T. 22 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

COUNTY SURVEYORS OFFICE

T 22 S

R	S 1	S 6	R
5	S 12	S 7	4
W		W	

 1959

from which the remains of two original bearing trees

A root hole, bears S. 18° E., 68 lks. dist., with a down fir alongside, 34 ins. diam., with fragmentary scribe marks visible on an opened blaze.

A root hole, bears N. 68° W., 64 lks. dist., with a down fir alongside, 40 ins. diam.; no marks visible.

and bearing trees mkd. by McGillicuddy

A cedar, 27 ins. diam., bears N. 16° E., 71 lks. dist., with fragmentary scribe marks visible on an open blaze.

A chinquapin, 18 ins. diam., bears S. 27 1/4° E., 21 1/2 lks. dist., with fragmentary scribe marks visible on an open blaze.

and a bearing tree mkd. by Byron

A fir, 19 ins. diam., bears N. 63 3/4° W., 20 lks. dist., with a healed blaze.

and a bearing tree mkd. by Shaner

A hemlock, 20 ins. diam., bears S. 26° W., 170 lks. dist., with a healed blaze.

and new bearing trees

A fir, 9 ins. diam., bears S. 34 1/2° E., 49 1/2 lks. dist., mkd. T22S R4W S7 BT.

A fir, 9 ins. diam., bears S. 26 3/4° W., 32 1/2 lks. dist., mkd. T22S R5W S12 BT.

N. 89° 25' W., bet. secs. 1 and 12, marking and blazing the true line.

Ascend over NE. slope, changing to SE. slope.

28.25

Ridge, bears N. 45° W. and S. 35° E.; desc. over SW. slope.

40.26

Point for the 1/4 sec. cor. of secs. 1 and 12, at proportionate dist.; there is no remaining evidence of the original cor.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.

T 22 S R 5 W

1/4 $\frac{S 1}{S 12}$

1982