

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional **17606**  
Lines, T. 21 S., R. 4 W., Willamette Meridian, Oregon

**CHAINS**

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 21 S	R 4 W
S 14	S 13
S 23	S 24
1982	

from which new bearing trees

A fir, 20 ins. diam., bears N. 47° E.,  
294 lks. dist., mkd. T21S R4W S13 BT.

An oak, 26 ins. diam., bears S. 50° E.,  
4 lks. dist., mkd. T21S R4W S24 BT.

A fir, 25 ins. diam., bears S. 23° W.,  
203 lks. dist., mkd. T21S R4W S23 BT.

An oak, 17 ins. diam., bears N. 50 1/2° W.,  
138 1/2 lks. dist., mkd. T21S R4W S14 BT.

Deposit corner stone alongside iron post.

N. 89° 21' W., bet. secs. 14 and 23, marking and blazing the true line.

Ascend over SE. slope, through scattering timber and moderate undergrowth.

19.945

Point for the E 1/16 sec. cor. of secs. 14 and 23.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16	S 14
	S 23
1982	

from which

An oak, 16 ins. diam., bears S. 56° E.,  
18 lks. dist., mkd. E 1/16 S23 BT.

A fir, 33 ins. diam., bears N. 28° W.,  
56 lks. dist., mkd. E 1/16 S14 BT.

From this point, an unrecorded point established by the Oregon State Highway Department, bears N. 87 1/4° E., 0.16 chs. dist., monumented with an iron rod, 5/8 in. diam., firmly set, projecting 3 ins. above ground.

Ascend over SE. slope.

24.00

Enter rock quarry, edge bears N. and S.

26.00

Spur, slopes N.; desc. over W. slope.

39.89

Point for the 1/4 sec. cor. of secs. 14 and 23, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron rod, 24 ins. long, 5/8 in. diam., 22 ins. in the ground.

No suitable trees available.