

County Surveyor's Record, Douglas County, Oregon

17645

Portion of Subdivisions of T. 31 S., R. 1 E.

CHAINS	
40.12	<p>Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for 1/4 sec. cor., with brass cap mkd.</p> <p style="text-align: center;"> $\frac{1}{4} \begin{array}{c} S 10 \\ S 15 \end{array}$ 1936 </p> <p style="text-align: right;">from which</p> <p>A fir, 15 ins. diam., bears N. 64° E., 72 lks. dist., mkd. 1/4 S 10 B T.</p> <p>A fir, 10 ins. diam., bears S. 20° E., 53 lks. dist., mkd. 1/4 S 15 B T.</p> <p>Asc. 720 ft. over SW. slope.</p>
65.80	Ridge, bears N. 10° E. and S. 10° W.; desc. 470 ft. over E. slope.
72.00	Enter heavy timber and light undergrowth, bears N. and S.
80.24	The cor. of secs. 10, 11, 14, and 15.
	<p>Land, mountainous. Soil, sandy loam; 2nd rate. Timber, fir, cedar, and pine. Undergrowth, willow, vinemaple, slickleaf, manzanita, Oregon grape, hazel, and bracken.</p>
	<p>N. 0° 05' E., bet. secs. 10 and 11.</p> <p>Over E. slope, through heavy timber and dense undergrowth.</p>
12.73	Spring, drains S. 60° E.; asc. 505 ft. over SE. slope.
40.00	<p>Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for 1/4 sec. cor., with brass cap mkd.</p> <p style="text-align: center;"> $\frac{1}{4} \begin{array}{c} \\ S 10 S 11 \\ \\ 1936 \end{array}$ </p> <p style="text-align: right;">from which</p> <p>A cedar, 25 ins. diam., bears S. 19 1/2° E., 51 lks. dist., mkd. 1/4 S 11 B T.</p> <p>A cedar, 17 ins. diam., bears S. 39° W., 60 lks. dist., mkd. 1/4 S 10 B T.</p> <p>Asc. 5 ft. over gradual S. slope.</p>
42.00	Divide, bet. Rogue River and South Umpqua River, bears N. 60° E. and S. 60° W.; road to Butler Butte, bears N. 30° E. and S. 60° W.; desc. 110 ft. over N. slope.
44.00	Forest Service Telephone line, bears E. and W.
45.80	Road to Butler Butte, bears NW. and SE.
47.65	Forest Service Road, bears NW. and E.
50.00	Enter opening, bears NW. and SE.
53.90	Draw, drains NW.; desc. 15 ft. along W. slope.
63.50	Enter scattering timber and light undergrowth.