

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of North Boundary  
 (Fifth Standard Parallel South), 17668  
 T. 23 S., R. 5 W., Willamette Meridian, Oregon

CHAINS							
	Ascend over SE. slope.						
26.40	Spur, slopes S. 50° E.; desc. over SW. slope.						
32.40	Ravine, drains S. 25° W.; asc. over SE. slope.						
32.60	Dirt road, 20 lks. wide, bears S. 50° E. and S. 60° W., in curve.						
39.83	<p>The standard cor. of secs. 4 and 5, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1959, determined at record bearing and distance from the remains of an original bearing tree</p> <p style="margin-left: 40px;">A sawed fir stump, 36 ins. diam., bears S. 58° E., 50 lks. dist., with fragmentary scribe marks visible on opened blaze.</p> <p>and bearing trees mkd. by Byron</p> <p style="margin-left: 40px;">A fir, 19 ins. diam., bears S. 46 1/4° E., 104 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A fir, 15 ins. diam., bears S. 16° W., 23 lks. dist., with healed blaze.</p> <p>At the corner point</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 33 ins. in the ground, the top 5 ins. below the surface of road, with aluminum cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 5</td> <td style="padding: 0 5px;">S 4</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">T 23 S</td> <td style="padding: 0 5px;">R 5 W</td> </tr> <tr> <td colspan="2" style="text-align: center; padding: 0 5px;">SC</td> </tr> </table> <p>1982</p> </div> <p>The corner is located in dirt road, 15 lks. wide, bears N. 25° W. and S. 25° E.</p> <p>Land, mountainous.                      Soil, rocky clay.                      Timber, fir, oak, hemlock, yew, madrone, ash, cherry, cedar, maple, alder, and chinquapin; undergrowth, poison oak, salal, Oregon grape, arrowwood, hazel, blackberry, huckleberry, salmonberry, wild rose, ferns, and young timber.</p>	S 5	S 4	T 23 S	R 5 W	SC	
S 5	S 4						
T 23 S	R 5 W						
SC							
	N. 89° 59' W., on the N. bdy. of sec. 5.						
	Ascend over SE. slope, through heavy timber and dense undergrowth.						
5.08	True point for the cor. of secs. 32 and 33 only, T. 22 S., R. 5 W., described in the field notes of the dependent resurvey of a portion of the subdivisional lines of T. 22 S., R. 5 W., executed concurrently under this same Group.						
26.95	Spur, slopes S. 10° W., desc. over broken SW. slope.						
32.60	Creek, 5 lks. wide, course S. 10° W.; asc. over SE. slope.						

FD OK 2-9A  
M118-66