

County Surveyor's Record, Douglas County, Oregon

17682

Dependent Resurvey, Portion of the Subdivisional Lines,
T. 22 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

Ascend over SE. slope.

27.60 Gravelled road, 20 lks. wide, bears N. 80° E. and W.

32.10 Ridge, bears N. 65° W. and S. 65° E.; desc. over NE. slope.

33.20 Dirt road, 20 lks. wide, bears N. 40° W. and S. 40° E.

39.48 The 1/4 sec. cor. of secs. 32 and 33, restored by person(s) unknown, recorded by Eugene A. Bloom, Registered Land Surveyor, No. 492, in 1981, and is accepted as the best available evidence of the position of the original corner, monumented with an iron rod, 5/8 in. diam., firmly set, projecting 8 ins. above ground, from which bearing trees mkd. by person(s) unknown

A fir, 10 ins. diam., bears N. 49° E., 19 lks. dist., with scribe marks 1/4 S33 BT visible on opened double blaze.

A fir, 29 ins. diam., bears N. 60 1/2° W., 43 lks. dist., with fragmentary scribe marks visible on partially healed double blaze.

(SEE HAINES F.B. #110)

At the corner point

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with aluminum cap mkd.

T 22 S	R 5 W
1/4	
S 32	S 33
1983	

Reset iron rod alongside aluminum post.

The corner is located in ravine, drains N. 60° E.

N. 0° 08' E., beginning new measurement.

Ascend over SE. slope.

5.15 Spur, slopes N. 60° E.; desc. over NE. slope.

7.30 Creek, 1 lk. wide, course S. 80° E.; asc. over SE. slope.

22.10 Dirt road, 20 lks. wide, bears N. 70° E. and S. 60° W.

25.50 Spur, slopes S. 85° E.; desc. over NE. slope.

39.56 The cor. of secs. 28, 29, 32, and 33, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1958, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 14 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 22 S	R 5 W
S 29	S 28
S 32	S 33

1958

from which the remains of original bearing trees