

County Surveyor's Record, Douglas County, Oregon

17685

Dependent Resurvey, Portion of the Subdivisional Lines,
T. 22 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

T 22 S R 5 W
1/4 $\frac{S 28}{S 33}$

1982

Reset iron rod alongside iron post.

S. 89° 09' W., beginning new measurement.

Ascend over SE. slope.

2.90 Spur, slopes S. 20° W.; desc. over SW. slope.

6.95 Ravine, drains S. 20° E.; asc. over broken SE. slope.

17.60 Spur, slopes N. 35° W.; desc. over broken NW. slope.

23.30 Ravine, drains N. 10° E.; asc. over broken NE. slope.

31.00 Spur, slopes N. 10° W.; desc. over NW. slope.

38.10 Ravine, drains N. 15° W.; asc. over NE. slope.

40.11 The cor. of secs. 28, 29, 32, and 33.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, oak, chinquapin, madrone, ash, maple, yew, and cherry: undergrowth, hazel, Oregon grape, salal, ferns, arrowwood, poison oak, blackberry, salmonberry, huckleberry, and young timber.

Subdivision of Section 33,
T. 22 S., R. 5 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of sec. 33 only, at proportionate distance, on the S. bdy. of the Tp.; there is no remaining evidence of the original corner.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.

T 22 S R 5 W
1/4 S 33

1983

from which

A cedar, 12 ins. diam., bears N. 45 3/4° E., 75 lks. dist., mkd. 1/4 S33 BT.

A fir, 6 ins. diam., bears N. 31 1/2° W., 25 lks. dist., mkd. X BT.

From this point, a locally established point, bears S. 28° 06' W., 0.234 chs. dist., monumented with an iron rod, 1/2 in. diam., firmly set, projecting 4 ins. above ground, from which bearing tree mkd. by person(s) unknown

A fir, 15 ins. diam., bears N. 73 1/2° E., 10 lks. dist., with healed double blaze.

*FDOK 2-99
118-66*

*SEE HAINES
F.B. #110
H. EN. 3*