

County Surveyor's Record, Douglas County, Oregon

17706

Dependent Resurvey, Portion of Subdivisional Lines,
T. 19 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

N 1/16
S 14 | S 13
1980

from which a new bearing tree

An alder, 16 ins. diam., bears N. 37 1/2° E.,
36 lks. dist., mkd. N 1/16 S13 BT on bark.

Set a 6 ft. steel fence post alongside the iron post.

N. 0° 48' E., beginning new measurement.

Ascend 170 ft. over SE. slope.

7.60 Ridge, bears N. 55° E. and S. 55° W.; desc. 200 ft. over NW. slope.

12.10 Gravelled road, 20 lks. wide, bears N. 55° E. and S. 55° W., also ravine, drains S. 55° W.; asc. 40 ft. over SE. slope.

16.70 Spur, slopes S. 70° W.; desc. 50 ft. over NW. slope.

20.02 The cor. of secs. 11, 12, 13, and 14, perpetuated by person(s) unknown, monumented with an iron bar, 5/8 in. diam., firmly set, projecting 5 ins. above ground, from which the remains of the original bearing trees

A root hole, bears N. 29 1/2° E., 14 lks. dist., with a rotted cedar stub, 22 ins. diam., alongside, with scribe marks R8 WS visible on opened blaze.

A cedar snag, 44 ins. diam., bears S. 4 1/2° E., 56 lks. dist., with healed blaze.

A sawed cedar stump, 48 ins. diam.; bears N. 5 1/2° W., 40 lks. dist., with healed blaze.

and locally mkd. bearing trees

A hemlock, 16 ins. diam., bears N. 70 1/2° E., 25 lks. dist., with scribe marks T19S R8W S12 BT visible on open blaze.

A cedar, 25 ins. diam., bears S. 9° W., 30 1/2 lks. dist., with opened and rotted blaze, no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, directly over the iron bar, with brass cap mkd.

T 19 S | R 8 W
S 11 | S 12
S 14 | S 13
1980

from which new bearing trees

A hemlock, 17 ins. diam., bears S. 51 3/4° E.,
39 lks. dist., mkd. T19S R8W S13 BT.