

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, 17716
T. 19 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

$$\begin{array}{cc} \hline W\ 1/16 & S\ 3 \\ T\ 19\ S & R\ 8\ W \\ \hline 1980 \end{array}$$

from which

An alder, 10 ins. diam., bears S. 29 3/4° E.,
68 lks. dist., mkd. W 1/16 S3 BT on bark.

A fir, 14 ins. diam., bears S. 72 1/2° W.,
167 lks. dist., mkd. W 1/16 S3 BT.

Set a 6 ft. steel fence post alongside the iron post.

From this point, the standard cor. of secs. 34 and 35,
T. 18 S., R. 8 W., bears S. 89° 45' E., 5.55 chs. dist.,
hereinbefore described.

Remonumentation of Certain Original Corner Points,
T. 19 S., R. 8 W., Willamette Meridian, Oregon

The following field notes describe the remonumentation of
certain original corner points, Township 19 South, Range
8 West, Willamette Meridian, Oregon, as provided for in
the General Special Instructions, Group No. 1000, dated
July 13, 1979, "Investigation of Physical Evidence of
Corner Positions and Accessories, Followed by Remonumen-
tation of Corner Points, with New accessories when
Needed".

Subdivision of T. 19 S., R. 8 W.,
Willamette Meridian, Oregon

(Remonumenting corners established by
Charles M. Collier, U.S. Deputy Surveyor, in 1891)

The 1/4 sec. cor. of secs. 13 and 24, determined from the
original bearing trees

A maple, 20 ins. diam., bears N. 13° E., 23 lks.
dist., with burned face outlined by old axe marks.

A fir, 33 ins. diam., bears S. 32° W., 30 lks.
dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in
the ground, with brass cap mkd.

$$\begin{array}{cc} T\ 19\ S & R\ 8\ W \\ 1/4 & \begin{array}{c} S\ 13 \\ S\ 24 \end{array} \\ \hline 1980 \end{array}$$

Set a 6 ft. steel fence post alongside the iron post.

he 1/4 sec. cor. of secs. 12 and 13, determined from the
remains of the original bearing trees