

County Surveyor's Record, Douglas County, Oregon

Remonumentation of Certain Original Corner Points,
T. 19 S., R. 8 W., Willamette Meridian, Oregon

17718

CHAINS

The 1/4 sec. cor. of secs. 1 and 12, determined from the remains of the original bearing trees

A sawed fir stump, 42 ins. diam., bears N. 1 1/2° W., 21 lks. dist., with scribe marks 1/4 S BT visible on opened double blaze.

A root hole, bears S. 45° W., 18 lks. dist., with a down and rotted fir, size indeterminate, alongside, no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with brass cap mkd.

T 19 S R 8 W
1/4 S 1
S 12
1980

from which new bearing trees

A fir, 8 ins. diam., bears N. 60° E., 18 1/2 lks. dist., mkd. 1/4 S1 BT.

A fir, 10 ins. diam., bears S. 12° E., 42 1/2 lks. dist., mkd. 1/4 S12 BT.

Set a 6 ft. steel fence post alongside the iron post.

The 1/4 sec. cor. of secs. 14 and 15, perpetuated by person(s) unknown, monumented with a steel fence post, 6 ft. long, firmly set, projecting 18 ins. above stream bed and debris, from which the remains of an original bearing tree

A hemlock, 65 ins. diam., bears S. 19° W., 125 lks. dist., with scribe marks BT visible on opened blaze.

and locally mkd. bearing trees

A cedar, 21 ins. diam., bears N. 36° E., 67 lks. dist., with scribe marks 1/4 S14 BT visible on partially healed blaze.

A maple, 33 ins. diam., bears S. 66° E., 80 lks. dist., with scribe marks 1/4 S14 BT visible on partially healed blaze.

A cedar, 35 ins. diam., bears N. 4 1/2° W., 168 1/2 lks. dist., with healed blaze.

and a reference monument

An iron post, 28 ins. long, 2 1/2 ins. diam., set 24 ins. in the ground, for a reference monument, bears S. 19° W., 40 lks. dist., with brass cap mkd. T19S R8W 1/4 S15 RM 40 LS 1980 and an arrow pointing to the corner.

Set a 6 ft. steel fence post alongside the reference monument.

The corner is located in creek, 4 lks. wide, course N. 20° E.