

# County Surveyor's Record, Douglas County, Oregon

Remonumentation of Certain Original Corner Points,  
T. 19 S., R. 8 W., Willamette Meridian, Oregon

17722

CHAINS

A fir, 35 ins. diam., bears N. 41° W., 26 lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 19 S    R 8 W  
1/4  $\frac{S 7}{S 18}$   
1980

Set a 6 ft. steel fence post alongside the iron post.

The 1/4 sec. cor. of secs. 7 and 8, perpetuated by person(s) unknown, monumented with an iron bar, 3/4 in. diam., firmly set, projecting 4 ins. above ground, from which an original bearing tree

A fir, 50 ins. diam., bears N. 66 1/2° W., 42 lks. dist., with scribe mark 4 visible on open blaze.

and a locally mkd. bearing tree

A sawed fir stump, 44 ins. diam., bears N. 61 3/4° E., 84 1/2 lks. dist., with scribe marks 1/4 S8 BT visible on partially healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, directly over the iron bar, with brass cap mkd.

T 19 S    R 8 W  
1/4  
S 7 | S 8  
1980

from which a new bearing tree

A hemlock, 20 ins. diam., bears S. 63 1/2° W., 48 lks. dist., mkd. X BT on double blaze.

No other suitable trees available within limits.

The corner is located approximately 25 lks. W. of creek, 1 lk. wide, course S.

The 1/4 sec. cor. of secs. 5 and 8, determined from the remains of the original bearing trees

A fir, 38 ins. diam., bears S. 21° E., 10 lks. dist., with scribe mark S visible in reverse and relief on overgrowth.

A root hole, bears N. 32 1/2° W., 28 lks. dist.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.