

# County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of the East One-Half Mile  
of the Line Between Sections 20 and 29, 17726  
T. 23 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

T 23 S    R 6 W  
S 20 | S 21  
S 29 | S 28  
1957

from which the remains of bearing trees mkd. by Gould, Gawron, and Eggen

A fir, 41 ins. diam., bears N. 79° E.,  
86 lks. dist., with healed blaze.

A fir snag, 25 ins. diam., bears S. 70° W.,  
17 lks. dist., with healed blaze.

A fir, 17 ins. diam., bears N. 11 1/2° W., 49 lks .  
dist., with healed blaze. (Record, N. 12 3/4° W.,  
31 lks.)

and new bearing trees

A fir, 10 ins. diam., bears S. 10 1/2° E.,  
121 lks. dist., mkd. T23S R6W S28 BT.

A fir, 6 ins. diam., bears S. 81 1/4° W.,  
121 lks. dist., mkd. T23S R6W S29 BT.

N. 89° 25' W., bet. secs. 20 and 29.

Ascend over SE. slope, through heavy timber and dense undergrowth.

5.65     Dirt road, 15 lks. wide, bears N. 50° E. and S. 75° W.,  
also ridge, bears N. 50° E. and S. 75° W.; desc. over NW.  
slope.

16.45     Head of ravine, drains N. 42° E.; asc. over SE. slope.

20.09     Point for the E 1/16 sec. cor. of secs. 20 and 29.

From this point, the E 1/16 sec. cor. of secs. 20 and 29, erroneously established by Gould, Gawron, and Eggen, in 1943-1957, bears S. 87° 47' W., 2.35 chs. dist., monumented with an iron post, 2 1/2 ins. diam., set, marked, and witnessed as described in the official record. I removed the iron post, destroy the marks on the bearing trees, and at the true corner point

Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16    20  
                  29  
                  1957  
                  1983

from which

A fir, 23 ins. diam., bears N. 54 1/2° E.,  
41 lks. dist., mkd. E 1/16 S20 BT.

A fir, 18 ins. diam., bears S. 62 1/2° W.,  
26 lks. dist., mkd. E 1/16 S29 BT.

Ascend over SE. slope.

28.70     Ridge, bears S. 20° E. and N. 10° W.; desc. over NW.  
slope.