

# County Surveyor's Record, Douglas County, Oregon

17735 Dependent Resurvey, Portion of the Subdivisional Lines,  
T. 23 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

N. 25° 10' E., bet. secs. 19 and 20.

Ascend over SE. slope, through heavy timber and dense undergrowth.

4.00 Ridge, bears NW. and SE.; desc. along E. slope.

7.50 Creek, 7 lks. wide, course S. 45° E.; asc. along broken E. slope.

32.60 Spur, slopes N. 35° E.; desc. over NE. slope.

43.44 The 1/4 sec. cor. of secs. 19 and 20, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

T 23 S    R 6 W  
          1/4  
          S 19 | S 20  
          1957

from which the remains of a bearing tree mkd. by Brooks

A root hole, bears N. 85° E., 54 lks. dist., with a down fir alongside, 24 ins. diam., no marks visible.

and bearing trees mkd. by the County Surveyors Office

A fir, 20 ins. diam., bears N. 30° E., 103 lks. dist., with healed double blaze.

A hemlock, 13 ins. diam., bears N. 2° W., 132 lks. dist., with scribe marks 1/4 S19 CS visible on partially healed blaze.

N. 25° 12' E., beginning new measurement.

Ascend over SE. slope.

2.45 Gravelled road, 15 lks. wide, bears N. 85° E. and S. 85° W., also ridge, bears N. 85° E. and S. 85° W.; desc. over broken NW. slope.

21.81 The N 1/16 sec. cor. of secs. 19 and 20, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

N 1/16  
S 19 | S 20  
1957

from which bearing trees mkd. by Brooks

A fir, 30 ins. diam., bears N. 84° E., 72 lks. dist., with healed blaze.

A fir, 12 ins. diam., bears N. 6 3/4° W., 103 lks. dist., with healed blaze.

N. 25° 09' E., beginning new measurement.

Descend over NW. slope.

2.80 Gully, drains NW.; asc. over SW. slope.

7.50 Head of gully, drains NW.; desc. over NW. slope.