

County Surveyor's Record, Douglas County, Oregon

17737 Dependent Resurvey, Portion of the Subdivisional Lines,
T. 23 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

Timber, fir, hemlock, cedar, madrone, maple, and alder;
undergrowth, salal, vine maple, poison oak, arrowwood,
and young timber.

Subdivision of Section 20,
T. 23 S., R. 6 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of secs. 20 and 29.

N. 22° 04' E., on the N. and S. center line of sec. 20.

Ascend over SW. slope, through heavy timber and dense
undergrowth.

19.30 Ridge, bears N. 50° W. and S. 30° E.; desc. over NE.
slope.

21.55 Dirt road, 15 lks. wide, bears S. 15° E. and N. 30° W.

36.20 Head of ravine, drains N. 85° E.; desc. over broken NE.
slope.

41.63 Point for the center 1/4 sec. cor. of sec. 20, at intersec-
tion with the E. and W. center line.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24
ins. in the ground, with aluminum cap mkd.

T 23 S R 6 W
 C 1/4
 S 20
 1983

from which

A fir, 18 ins. diam., bears S. 66° W., 24
lks. dist., mkd. X BT.

A fir, 20 ins. diam., bears N. 39 1/2° W., 10
lks. dist., mkd. C 1/4 S20 BT.

Descend over broken NE. slope.

62.10 Ravine, drains E.; asc. over SE. slope.

62.76 Point for the center N 1/16 sec. cor. of sec. 20.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in
the ground, with brass cap mkd.

 C
N 1/16 | S 20
 C
 1983

from which

A hemlock, 10 ins. diam., bears N. 69° E.,
43 lks. dist., mkd. CN 1/16 S20 BT.

A cedar, 10 ins. diam., bears S. 62 1/2° W.,
47 lks. dist., mkd. CN 1/16 S20 BT.

Ascend over SE. slope.

64.40 Spur, slopes E.; desc. over NE. slope.