

County Surveyor's Record, Douglas County, Oregon

17742

Subdivision of Section 26,
T. 23 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	<p>At the corner point</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.</p> <div style="text-align: center;"> $\begin{array}{c} C \\ N\ 1/16 \quad \quad S\ 26 \\ C \\ 1982 \end{array}$ </div> <p>from which a new bearing tree</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears S. 20 1/2° E., 84 lks. dist., mkd. CN 1/16 S26 BT.</p> <p style="padding-left: 40px;">Reset iron rod alongside iron post.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 1° 00' W., beginning new measurement.</p> <p>Descend over NE. slope.</p>
1.60	Creek, 5 lks. wide, course S. 80° E.; asc. over SW. slope.
19.06	The 1/4 sec. cor. of secs. 23 and 26.
	<p>From the 1/4 sec. cor. of secs. 25 and 26. S. 89° 43' W., on the E. and W. center line of sec. 26. Descend over broken NW. slope, through heavy timber and dense undergrowth.</p>
20.05	Dirt road, 25 lks. wide, bears N. 10° E. and S. 60° W., in curve.
20.39	<p>Point for the center E 1/16 sec. cor. of sec. 26.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> $\begin{array}{c} C \quad E\ 1/16 \quad C \\ \quad \quad S\ 26 \\ \quad \quad 1982 \end{array}$ </div> <p>from which</p> <p style="padding-left: 40px;">A fir, 6 ins. diam., bears N. 17° E., 27 lks. dist., mkd. X BT.</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears South, 13 1/2 lks. dist., mkd. CE 1/16 S26 BT.</p> <p>Descend over NW. slope.</p>
20.50	Creek, 1 lk. wide, course N. 40° W.; desc. over broken NW. slope.
40.78	<p>The center 1/4 sec. cor. of sec. 26.</p> <p>Descend over broken NW. slope.</p>
46.90	Yellow Creek, 20 lks. wide, course S. 60° W.; asc. over SE. slope.