

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 28 S., R. 7 W., Willamette Meridian, Oregon

17754

**CHAINS**

S. 89° 59' W., beginning new measurement.

Continue over nearly level land along Larson Road.

15.00 Leave Larson Road, asphalt surface, 35 lks, wide, bears E. and S. 70° W.; asc. broken SE. slope.

19.89 The 1/4 sec. cor. of secs. 4 and 9, perpetuated and recorded by G.C. Stewart, Deputy Douglas County Surveyor, in 1922, from original evidence no longer in existence, and further perpetuated and recorded by James W. Byron, Deputy Douglas County Surveyor, in 1961, monumented with an iron pipe, 1 1/4 ins. diam., projecting 8 ins. above the ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 28 S    R 7 W

1/4  $\frac{S 4}{S 9}$

1961

from which the remains of bearing trees mkd. by Byron

A pine stump, 9 ins. diam., bears S. 9° W.,  
34 lks. dist., with marks S9 CS BT visible  
on an opened blaze.

A rotted fir stump, 15 ins. diam., bears N. 18° W.,  
51 lks. dist., no marks visible.

and new bearing trees

A fir, 8 ins. diam., S. 59 1/4° E., 38 lks.  
dist., mkd. 1/4 S9 BT.

A fir, 13 ins. diam., bears N. 28 1/2° W., 95 1/2 lks.  
dist., mkd. 1/4 S4 BT.

N. 83° 10' W., beginning new measurement.

Descend over SW slope.

1.45 Gravel road, 20 lks. wide, bears N. and S.

15.45 Creek, 8 lks. wide, course S. 20° E.; asc. SE. slope.

18.88 The W 1/16 sec. cor. of secs. 4 and 9, established and recorded by Herbert L. Northcraft, Registered Land Surveyor, No. 750, in 1974, and accepted as the cor., monumented with an iron rod, 5/8 in. diam., projecting 6 ins. above the ground, from which the bearing trees mkd. by Northcraft

A fir, 14 ins. diam., bears S. 53° W., 6 lks.  
dist., with a healed blaze.

A cedar, 8 ins. diam., bears S. 53° W., 20 lks.  
dist., with a healed blaze.

A cedar, 8 ins. diam., bears N. 44° W., 44 lks.  
dist., with a healed blaze.