

# County Surveyor's Record, Douglas County, Oregon

17755 Dependent Resurvey, Portion of Subdivisional Lines  
T. 28 S., R. 7 W., Willamette Meridian, Oregon

**CHAINS**

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, directly atop the iron rod, with brass cap mkd.

W 1/16  $\frac{S 4}{S 9}$

1983

N. 83° 10' W., beginning new measurement.

Ascend NE. slope.

- 9.32 Creek, 8 lks. wide, course N. 45° E.; asc. SE. slope.
- 10.32 Top of rock bluff, 45 ft. high, edge bears N. 35° E. and S. 35° W.; asc. SE. slope.
- 18.22 Dirt road, 15 lks. wide, bears N. 51° E. and S. 51° W.
- 18.85 The cor. of secs. 4, 5, 8, and 9.

Land, mountainous.  
Soil, rocky clay.  
Timber, pine, fir, cedar, oak, madrone, maple, hemlock, alder, and ash; undergrowth, poison oak, vine maple, blackberry, huckleberry, arrowwood, hazel, salal, fern, and young timber.

From the cor. of secs. 8, 9, 16, and 17.

N. 89° 49' W. , bet. secs. 8 and 17.

Asc. NW. slope, through heavy timber and dense undergrowth.

- 1.05 Spur, slopes N. 40° W.; desc. broken W. slope.
- 20.48 Point for the <sup>E</sup>W 1/16 sec. cor. of secs. 8 and 17.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with brass cap mkd.

9-21-93

W 1/16  $\frac{S 8}{S 17}$   
1983

Actually E 1/16  
B.L.M. aware of  
Problem - Resurvey  
Pending in Portland  
JC

from which

A fir, 10 ins. diam., bears N. 87 1/2° E., 19 lks. dist., mkd. W 1/16 S8 BT.

A cedar, 5 ins. diam., bears S. 50° W., 45 lks. dist., mkd. W 1/16 S17 BT.

- 20.55 Ravine, drains S. 45° W.; asc. broken SE. slope.
- 40.96 The 1/4 sec. cor. of secs. 8 and 17, reestablished by proportionate dist. and recorded by Virgil L. Broadwater, Registered Land Surveyor, No. 682, in 1972, monumented with an iron pipe, 1 1/2 ins. diam., firmly set, projecting 8 ins. above the ground. There is no remaining evidence of the original cor. This position is accepted as the cor., from which bearing trees mkd. by Broadwater